Gen Menters

RAAUZEXW RULNNAC1187 8981158-UUUU--RUWMDTA:
ZNR UUUUU
R 281228Z APR 77 ZEX
FM ODR ARNG-OAC EDGEWOOD MD //NGB-AVN-L//
TO A1G 7481
INFO RUEADMD/CNGB WASH DC //CNGB-ARL-A//
R 272835Z APR 77
FM ODR USAAVSCOM STL MO //DRSAV-FEG//
TO A1G 8881
BT
UNCLAS
NOTE - THIS MESSAGE HAS NOT, REPEAT HAS NOT, BEEN T

UNCLAS
NOTE - THIS MESSAGE HAS NOT, REPEAT HAS NOT, BEEN TRANSMITTED TO
UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES ARE RESPONSIBLE FOR
DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES,
ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED, RETRANSMITTAL

SHALL REFERENCE THIS MESSAGE.
SUBJ - MAINTENANCE ADVISORY MESSAGE CONCERNING ALL ARMY AIRCRAFT
UTILIZING ROTARY AIRCRAFT MOTOR GENERATORS (INVERTERS). (GEN-77-18)

THIS IS A TRANSMITTAL OF INFORMATION RECEIVED FROM ECOM/
RSEL-MA-DT TOGETHER WITH INFORMATION FROM THIS HEADQUARTERS;
DELETE LISTING OF ROTARY INVERTERS FROM TB 55-1500-307-24,
18 JUNE 1976 AS A TRO ITEM AND DISREGARD INSTRUCTIONS IN THE EIR

PAGE 2 RULNNAC1187 UNCLAS DIGEST ITEMS PUBLISHED IN TO 43-0001-9-2, JUNE 1975, TO SEND ALL INVERTERS TO DEPOT FOR OVERHAUL AFTER EVERY 988 FLIGHT HOURS OF SERVICE, TH 55-1518-284-28 SERIES MANUALS FOR THE OV-18. C AND D AIRCRAFT WILL BE REVISED TO REFLECT THIS CHANGE. 3. A SIGNIFICANT INCREASE IN THE INVERTERIS ITY HAS RESULTED FROM THE IMPLEMENTATION OF STRINGENT DEPOT OVERHAUL STANDARDS WHICH INCLUDES A REQUIREMENT TO ONLY INSTALL HIGH SPEED MS-TYPE BEARINGE, THIS PROGRESS; AS VERIFIED BY THE RECENT SURVEY, NOW MARRANTS CLASSIFICATION OF THE ROTARY INVERTER AS A "CONDITION ITEM" INSTEAD OF A "TIME CHANGE" ITEM, HOHEVER; SUCCESS OF THIS POLICY REQUIRES THAT EACH USER ORGANIZATION PERFORM SCHEDULED MAINTENANCE AND SEND INVESTERS TO DEPOT FOR OVERHAUL WHEN INDICATED BY SPECIFIED CONDITIONS. PERIODIC OR PHASE INSPECTION, OR 188 FLIGHT HOURS, WHICHEVER COMES FIRST CLN

REMOVE THE INVERTER AND SEND TO AVIONIOS DIRECT SUPPORT MAINTENANCE;
B. AVIONIOS DIRECT SUPPORT MAINTENANCE - CLEAN AND INSPECT INVERER FOR CRACKED OR DAMAGED CASE, AND BROKEN CONNECTOR PINS OR CRACKED

CONNECTOR INSERTS. INSPECT THE BRUSHES FOR HEAR, ONE AT A TIME SO
THEY ARE PROPERLY RE-INSTALLED IN THE SAME BRUSH HOLDER; HEAR TO
THE RECOMMENDED END OF THE WEAR MARK (A 1/32-INCH WIDE DIAGONAL)
GROOVE IN THE BOTTOM HALF (HIDTH) OF THE BRUSH OR A PARALLEL GROOVE
IN THE TOP EDGE OF THE BRUSH) MILL GIVE AT LEAST SEE INVERTER
OPERATIONAL HOURS AT FULL LOAD. INSPECT THE BRUSH CONTACT AREA
THE COMMUTATOR AND SLIP RINGS FOR SERIOUS GROOVING AND PITTING; A
CONDITION REGUIRES BRUSH RUN-IN FOR PROPER SEATING. HHILE
USING MOTOR GENERATOR TEST SET ANYOSM-65; APPLY 1/4 TO 1/3 FULL
RATE LOAD FOR 2 HRS; THEN FULL LOAD UNTIL DO BRUSHES ARE SEATED
188P/C IN DIRECTION OF ARMATURE ROTATION AND 78P/C OF BRUSH
THICKNEHM.
AC BRUSHES REQUIRE SEATING TO SEP/O OF BRUSH CONTACT AREA,
PERFORM OPERATIONAL TEST SET ANYOSM-65; APPLY 1/4 TO 1/3 FULL
REGULATION OF THE INVERTER FOR THREE PHASE DELTA OPERATION USING
MOTOR GENERATOR TEST SET ANYOSM-65 TO 27.5 VDC; ADJUST
THE TEST SET LOAD REGULATOR CONTROL FOR A READING ON THE AC AMP
METER EQUAL TO ONE-HALF THE INVERTER'S FULL LOAD; AND ADJUST (IF

JESSARY) THE INVERTER'S VOCTAGE AND FREQUENCY POTENTIONETERS FOR METER READINGS OF 115 VAC AND 400 HZ; TIGHTEN ADJUSTMENT LOCKNUTS; (B) INCREASE THE VOCTAGE APPLIED TO AN/ASM-65 TO 29 VDC; AND SET THE COAD REGULATOR CONTROL TO 0; RECORD THE OUTPUT VOCTAGE AND FREQUENCY.

(C) REDUCE THE APPLIED VOLTAGE TO 26 VDC, ADJUST THE LOAD REGULATOR CONTROL FOR AN AC AMPS READING EQUAL TO FULL LOAD; RECORD THE OUTPUT VOLTAGE AND FREQUENCY. THE REGULATION STANDARDS REQUIRED FOR THIS TEST ARE AS FOLLOWS - VOLTAGE 115 PLUS/MINUS 2-1/2 VAC; FREQUENCY 400 PLUS/MINUS 10 HZ, THE TESTS LISTED IN MANUALS FOR RANGE OF ADJUSTMENT OF OUTPUT VOLTAGE AND FREQUENCY AND FOR OVERSPEED ARE TO BE OMITTED.

C. AVIONICS GENERAL SUPPORT MAINTENANCE - BEARING REPLACEMENT.
THIS COMPONENT HAS A CRITICAL EFFECT UPON THE INVERTER'S RELIABILE.
ITY AND SERVICE-LIFE, THEREFORE, IT IS MANDATORY THAT ONLY THE
FOLLOWING TWO MS TYPE HIGH-SPEED BEARINGS BE INSTALLED IN THE
APPLICABLE INVERTER - (A) BEARING NSN 3118-88-186-8543 IN PU-5431/A
(ALL MODELE), PU-544A/A (BENDIX MODEL), & PU-733/A (AMP "LELAND"
MODEL); (B) BEARING NSN 3118-88-689-7392 IN THE FOLLOWING POURAMP

PAGE 5 RULNNADI187UNGLAS

544/A, PU-545/A, PU-572/A, AND PU-573/A.

D. OPERATIONAL RELIABILITY DEPENDS UPON EXERCISING PROPER JUDGMENT WHEN TO TURN IN THE INVERTER FOR DEPOT OVERHAUL. INVERTERS SHOULD NOT BE OPERATED TO FAILURE, THEREFORE?

IT IS ESSENTIAL TO TURN IN FOR DEPOT OVERHAUL ANY INVERTER WHICH VIBRATES TOO MUCH, OVERHEATE, IS UNUSUALLY NOISY, OR HAS A BRUSH CONTACT AREA ON THE COMMUTATOR AND/OR SLIP RINGS THAT EXHIBITS SERIOUS GROOVING OR PITTING. 3. THE APPROPRIATE ECOM AND AVSCOM MANUALS/PUBLICATIONS WILL BE REVISED TO REFLECT THE ABOVE INFORMATION, EVENTUALLY, EVERY INVERTER, AS A RESULT OF IMPLIMENTING THIS POLICY, WILL EXHIBIT CONDITIONS THAT WILL REQUIRE REPAIR AND/OR DEPOT OVERHAUL. HOWEVER, SINCE THIS INEVITABLE OCCURRENCE WILL BE NORMALLY EXPECTED EVENT, SUBMISSION OF AN EIR WILL NOT BE REQUIRED EXCEPT FOR UNWARRANTED OR UNUSUAL OCCURRENCES. 7. INSERT INFORMATION CONTAINED IN THIS MESSAGE IN THE APPROPRIATE THS UNTIL RECEIPT OF THE FORMAL CHANGE. 8. POINT OF CONTACT FOR INFORMATION ON THE INVERTERS IS MR. JOE PAWLAK, ECOM, AUTOVON 992-1309. PT #1107

20

NNN