MESTERN UNION C.R.C. MCLB DRAWER 38 ALBANY GA 31704 27AM



4-005846A119 04/89/91 ICS DUDCRSA ABN BESC 06445 DOD CRC ALBANY GA 2919082 APR 91/119

USDA FOREST SVC AVIATION FIRE MGMT 1905 VISTA AVE 801SE ID 83705 Mederis Asmol

I R RUCIFRD5521 1191828 DA-BDCVBA
R 2920002 APR 91 ZEX
FM CDRAVSCOM ST LOUIS MO //AMSAV-XSOF//
FO RUCLRFA/USDA FOREST SERVICE AVIATION FIRE MGMT
//3905 VISTA AVE BOISE ID 83705//
DA-BDCVBA
UNCLAS
SECTION 01 0F 02

SUBJECT - AVIATION SAFETY ACTION MESSAGE, INFORMATIONAL, ALL UH-1 SERIES AIRCRAFT, ALTERNATE METHOD OF TRACKING TAIL ROTOR BLADES USING FIXED LENGTH TAIL ROTOR PITCH CHANGE LINKS. (UH-1-91-ASAM-OB)

NUTE - THIS IS AN AVIATION SAFETY ACTION MESSAGE AND HAS NUT BEEN PAGE OF RUCIFRD5521 UNCLAS

TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSES. ADDRESSES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THE MESSAGE.

- 1. PRIORITY CLASSIFICATION -
 - A. AIRCRAFT IN USE N/A.
 - B. AIRCRAFT IN DEPOT MAINTENANCE N/A.
 - C. AIRCRAFT UNDERGUING MAINTENANCE N/A.
 - D. AIRCRAFT IN TRANSIT -
 - (1) SURFACE/AIR SHIPMENT N/A.
 - (2) FERRY STATUS N/A.
 - E. MAINTENANCE TRAINERS (CATEGORY A. B AND C) N/A.
- F. COMPONENT/PARTS IN STOCK INCLUDING WAR RESERVES AT ALL LEVELS (DEPOT AND OTHERS) N/A.
- E. JASK/INSPECTION SUSPENSE DATE N/A.
- 3. REPORTING COMPLIANCE SUSPENSE DATE N/A.
- -. SIMHARY OF PROBLEM -
- A. THE NEW ROTOR BLADE TRACK AND BALANCE CONTRMENT CURPENTLY
 BEING (SSUED TO THE FIELD DOES NOT INCLUDE STRORE LIGHT PROVISIONS
 OF ALLOW VISUAL TRACKING OF THE UH-1 TAIL ROTOR. THEREFORE AN
 PAGE OF RUCLEROSSEL UNC. AS
 - ALTERNATE NETHOD FOR SETTING THE PITCH LINES ON THE TAIL ROTOR BLADES HAS BEEN DEVELOPED.
 - 8. RESEARCH AND TESTS HAVE SHOWN THAT SETTING THE RITCH LIBER 17 A FIRET LENGTH ACCOMPLISHES TAIL ROTOR TRACKING. 1. THE FURDISE OF THIS MESSAGE IS 10 ADVIDE THE TIEL OF AN

To reply by Mailgram Message, see reverse side for Western Union's toll-free numbers.



ALTERNATE PROCEDURE FOR SETTING THE TAIL ROTOR PITCH CHANGE

- 5. END ITEMS EFFECTED ALL UH-1 SERIES AIRCRAFT.
- 6. ASSEMBLY COMPONENTS EFFECTED -

NOMENCLATURE PART NO.

TYP LINK ASSY

NSN

204-011-762-11

3040-00-157-5087

- 7. PARTS TO BE INSPECTED N/A.
- 8. INSPECTION PROCEDURES N/A.
- 9. CORRECTION PROCEDURES
- A. THE CHANGES TO TM 55-1520-210-23-1 AND TM 55-1520-220-23-1 ARE AS FOLLOWS
- (1) CHANGE THE FIRST NOTE AFTER PG 5-147, PARA 5-124 OF TM 55-1520-220-23 1 AND PG 5-148, PARA 5-136 OF TM 55-1520-220-23 1 TO
- "AFTER REPLACEMENT OR INSTALLATION OF TAIL ROTOR HUB BLADES OR PITCH CHANGE SYSTEMS, CHECK TAIL ROTOR RIGGING AND SET PITCH LINKS PAGE 04 RUCIFRD5521 UNCLAS
- 10 2.11 INCHES BETWEEN THE JAM NUTS. TAIL ROTOR TIP CLEARANCE SHALL BE CHECKED AND BOTH PITCH LINKS ADJUSTED IF NECESSARY. THIS PROCEDURE MAY BE USED INSTEAD OF TRACKING THE TAIL ROTOR BLADES USING A STROBE LIGHT.
- (2) CHANGE THE FIRST NOTE AFTER PG 5-140, PARA 5-139 OF TM 55-1520-210-23-1 AND PG 5-148, PARA 5-136 OF TM 55-1520-220-23-1 TD READ
- "TAIL ROTOR MUST BE IN TRACK OR PITCH LINKS SET TO 2.11 INCHES BETWEEN JAM NUTS BEFORE BALANCING."
- B. THE CHRRENT PROCEDURE FOR TRACKING THE TAIL ROTOR BLADES IS NOT BEING REMOVED FROM THE ABOVE MANUALS. INTRODUCTION OF THE ALTERNATE PROCEDURE DOES NOT PRECLUDE UNITS FROM USING THE CURRENT PROCEDURE AS LONG AS THE EQUIPMENT TO PERFORM TRACKING IS AVAILABLE. 10. SUPPLY/PARTS AND DISPOSITION - N/A.
- 11. SPECIAL TOOLS, JIGS AND FIXTURES REQUIRED N/A.
- 12. APPLICATION -
 - A. CATEGORY OF MAINTENANCE AVUM.
 - B. TIME REQUIRED N/A.
- C. TB/NWOS TO BE APPLIED PRIOR TO DR CONCURRENTLY WITH THIS INSPECTION - N/A.
- PAGE 05 RUCIPPD5521 UNCLAS
- D. PUBLICATIONS WHICH REQUIRE CHANGE AS A RESULT OF THIS MESSAGE TM 55-1520-210-23-1 ANT TM 55-1520-220-23-1 SHALL BE CHANGED TO REFLECT THIS MESSAGE. A COPY OF THIS MESSAGE SHALL BE INSERTED IN THE APPROPRIATE TH AS AUTHORITY TO IMPLEMENT THE CHANGE UNTIL THE PRINTED CHANGE IS RECEIVED.
- 13. REFERENCES -

14:80 EST