It's not a wrinkle! That tinkling sound inside the UH-1 and AH-1 tail rotor blades is normal and to be expected. When the aluminum

LAST

NITE!

of balance weights, some of the metallic residue can't be removed.

honeycomb is drilled for installation