

*Wgn locked keys*  
*GEN-76-6*  
5 FEB 76 14 34z

RAAUZEXW RULNEAA0730 0361338-UUUU--RUWMDTA!  
ZNR UUUUU

R 051323Z FEB 76 ZEX

FM ARNG OAC EDGEWOOD MD //OAC-AVN-L//

TO AIG 7401

INFO RUEFHQA/ONGB WASH DC//NGB-ARL-A//

R 041450Z FEB 76

FM CDR USAAVSCOM STL MO //DRSAV-FEG//

TO AIG 8881

INFO AIG 9004

BT

UNCLAS

NOTE THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES; ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED; THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE;

SUBJ CLN MAINTENANCE ADVISORY MESSAGE ON AIRCRAFT IGNITION

LOCK-OUT SWITCH AND KEYS (GEN 76-6)

A. USAREUR MSG 021638Z FEB 76, SUBJECT AS ABOVE;

1. PURPOSE OF MESSAGE CLN TO PROVIDE PROCEDURES FOR REPLACEMENT OF SUBJECT SWITCH/KEYS ON ARMY AIRCRAFT;

PAGE 2 RULNEAA0730 UNCLAS

2. REFERENCE A REQUESTED PROCEDURES BE PROVIDED AS RELATED TO POSSIBLE LOSS OF KEYS FOR AIRCRAFT IGNITION LOCK-OUT SWITCHES; SINCE THE LOSS OF A KEY COMPROMISES THE SECURITY OF THE ASSOCIATED AIRCRAFT, THE ENTIRE SWITCH ASSEMBLY (NSN 2925-00-552-5747) SHOULD BE REMOVED AND REPLACED; THE REMOVED SWITCH AND REMAINING DUPLICATE KEY IF ANY, SHOULD BE DISPOSED OF LOCALLY;

3. THE SWITCH ASSEMBLY IS IN THE ARMY SYSTEM AS A PEMA FUNDED ITEM AND IS APPLICABLE TO ALL AIRCRAFT IDENTIFIED IN THE ELECTRICAL IGNITION SECURITY DEVICE MWO S;

4. ALL APPLICABLE REPAIR PARTS AND SPECIAL TOOLS LIST (RPSTL) MANUALS WILL BE REVISED TO SHOW THE IGNITION LOCK-OUTSWITCH NSN;

BT

#0730

ARMY

10  
3