

RU NNACR209 8231006 KUUU-10UMQTB1

ND ((NOB:AVN:LY))
NO ((RRSTS:KEA:2))

army

REPEAT
TO ALL ADDRESSES
THIS MESSAGE IS
CONCERNING THE
REPAIR OF THE
MOTOR AND THE
ADJUSTMENT OF
THE PITCH OF
THE LINKS.
THE MOTOR SHOULD BE
CHANGED IN ENTIRETY
AND THE LINKS MUST BE
ADJUSTED EVENLY ONE TURN AT
A TIME.

*ut
T/A*

SHORTENING OF PITCH
AND INK CORRECTION
LOGISTICS RECIPIENTS:
MR. RAY BOLAND

2