


THE SPLIT CONE BIT



Some Huey and Cobra pitch pullers and knucklebusters get uptight when the split cones supporting the main and tail rotors slip.

Sure, the pubs call for equal spacing of the cone halves during installation. But the pubs don't call for maintaining that spacing during inspections.

So, don't sweat it if the cone gaps are not equal or one half of a cone touches the other half.