



Comes the time for a tail rotor control cable replacement in your Huey, the cable retaining pin in the parts pub may be too short.

The use of pin, NSN 5315-00-811-1266—Item 1, Fig 362 in TM 55-1520-210-23P—won't let you install a cotter key if the depot installed an oversize bushing in the quadrant.

In that case, bird mechs, you want pin, NSN 5315-00-812-3757.

