

ROTUZEXH RULNET00053 2121708-UUUU-TRUMMDTA

ZNR UUUUU

R 301210Z JUL 80 ZEX

FM ARNG OAC EDGEWOOD MD //NGB-AVN-L//

TO AIG 7485

AIG 7485

RULGOML/USPFO VI ST CROIX VI

INFO RULNNHG/MACE MD HAYRE DE GRACE MD

R 251545Z JUL 80

FROM CDRTSARCOM STL MO //DRSTS-SAJT//

BT

UNCLAS

SUBJ REPAIR CAPABILITY OF TURBINE NOZZLE, NSN 2840-00-570-9883

1. DUE TO EXTREME SUPPLY SHORTAGE OF THE T53-L-113B-N1 TURBINE NOZZLE, OACAD HAS DEVELOPED SEVERAL INNOVATIVE REPAIR TECHNIQUES WHICH HAVE SUCCESSFULLY RESTORED THE MAJORITY OF NOZZLES TO SERVICEABLE CONDITION.

2. REQUEST ALL MAINTENANCE AND SUPPLY PERSONNEL BE ADVISED TO STOP DISPOSING OF UNSERVICEABLE NOZZLES. THE NEXT AMDE BROADCAST SHOULD CONFIRM THE RECOVERABILITY CODE CHANGE TO "DBPOT".

3. ALL UNSERVICEABLE NOZZLES SHOULD BE PACKAGED AND SHIPPED DIRECT TO THE NIOP ACCOUNT AT CORPUS CHRISTI ARMY DEPOT, CORPUS CHRISTI.

PAGE 2 RULNET00053 UNCLAS

TEXAS:

4. ALL ACTIVITIES WITH UH-1M, UH-1H, AH-60, OV-10, OV-10 AND RV-10 AIRCRAFT ARE AFFECTED.

5. POO AT TSARCOM IS MRS. IRENE LATZMAN, AUTOVON 693-3738.

BT

#0053

Army

*Message
301210Z
Turbine
TS3*

30 Jul 80 18 09z

27

NNNN