

IT'S A STANDOFF

If your Delta or Hotel model Hueys have the crashworthy fuel system per MWO 55-1520-210-50/1, look at the main fuel lines. Could be lines FSN 4720-176-4612 are about to chafe and wear a hole in the transmission sump.

Head off downtime by using clamps or rerouting the lines for $\frac{1}{2}$ -in minimum clearance.

A flashlight and mirror will make your inspection easier.

