

07EXH RUEBADA0356 3072100-UNCLAS
ZNY UNCLAS

R 032034Z NOV 75 ZEX

FM ARND OAC EDGEROOD MD //OAC-AMN-1//

TO ATG 7101

INFO RUEFHQA/ONCR WASHDC //NSG-ARL-4//

R 011552Z OCT 75

FM CDR USATROSCOM STL MO

TO CINCPAC SPT GRP FT SHAFTER HI

CINCSAREUR HEIDELBERG GER

CDR USABIGHT SEOUL KOREA

CHUSALOG ASST OFC PAC FT SHAFTER HI

CHUSALOG ASST OFC RUP HEIDELBERG GER

CDR USANT SCHOFIELD BKS HI

CDR USARJ CP ZAMA JAPAN

CDR USAKORSCOM TAEJU KOREA

CDR FORSCOM FT MONROE VA

CDR USARLOGSPT FT AMADOR CA

CDR USARJL FT RICHARDSON AK

CDR USAONE FT MEADE MD

CDR MCB WASH DC

CDR USAFIVE FT SAN HOUSTON TX

*file extinguisher
Gen-75-10*

R 02 RUEBADA0356 UNCLAS

FM USASIX SAN FRANCISCO CA

CHUSALOG ASST OFC (AMC) SEOUL KOREA

CHUSALOG ASST OFC (AMC) SUKIPAT OKINAWA

USCINCPAC MACDILL AFB FL

CDR USARSCOM NAGAHATA OKINAWA

CDR TRADOC FT MONROE VA

CDR USAHC ALEX VA

BT

UNCLAS

OPDU CLN FIRE EXTINGUISHER, NONGPROTREFLUOROMETHANE, 2 3/4

LT., NSN 4210-00-555-8437.

1. THIS COMMAND IS IN RECEIPT OF CIR INDICATING SUBJECT
FIRE EXTINGUISHER EXPLODED AND CAUSED DAMAGE TO AIRCRAFT
LITTING ON RAHP IN 104 DEGREES F AMBIENT TEMPERATURE.

2. SUBJECT FIRE EXTINGUISHER CYLINDER IS NOT TO BE
REFILLED UNDER ANY CONDITION. WHEN DISCHARGED, DISCARD
EMPTY CYLINDER AND REPLACE WITH NEW CHARGED CYLINDER,
NSN 4210-00-708-0031, OBTAINED FROM SUPPLY SYSTEM.

3. CYLINDER NSN 4210-00-708-0031 IS A THROW-AWAY ITEM.
RECHARGING IT IS NOT ALLOWED FOR SAFETY AND ECONOMICAL

(16)

PAGE 3 BUEBADA0350 UNCLAS

REASONS IN ACCORDANCE WITH POLICY ESTABLISHED IN PARAGRAPH
7B OF TB 5-4200-200-10, DATED 14 MARCH 1974.

IN ADDITION TO ABOVE, REQUEST ALL SUBJECT EXTINGUISHERS
BE INSPECTED FOR DISTORTED OR SWOLLEN CYLINDERS, IF ANY
ARE FOUND REMOVE FROM SERVICE IMMEDIATELY, DISCHARGE
CHEMICAL AND REPORT TO THIS COMMAND, ATTN CLN AMSTS-MMR,

BT

#0350

NNNN