

29 AUG 79 00 35z

(22)

ARMY

MA
Rau

OTUZEXW RULNNAQ2279 2422254-UUUU--RUKMDTA,

NR UUUUU

P 281928Z AUG 79 ZEX

M NDR ARNG DAC EDGEWOOD AREA APO MD //NOB-AVN-L//

O +AIG 7421

P 281928Z AUG 79 ZFF-4

M ODR USATSARCOM SIL MD //DRSTS-HEA(2)//

O AIG 8881

IG 7519

UEBDDA/US ENV PROTECTION AGY REGION II 26 FEDERAL PLAZA NY NY

UWNSSS/US ENV PROTECTION AGY PO BOX 15227 LAS VEGAS NV

UOFC RSCH DEV ENV MONITORING AND SPT LAB/MD//

UEBPAA/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD

UOAAA/OA2//

NFO AIG 9284

IG 7514

UCLEUA/CDR USAAVNO FT RUCKER AL //ATZQ-DI//

BT

UNCLAS E F T O

IOAA/OA2 FOR COL L A HEAVER

NOTE THIS IS A SAFETY OF FLIGHT MESSAGE AND HAS NOT, REPEAT HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.

PAGE 2 RUKTFEC4953 UNCLAS E F T O

SUBJECT: CHANGE TO SAFETY OF FLIGHT MESSAGE - ONE TIME INSPECTION OF UH-1 SERIES HELICOPTER TAIL ROTOR HUB ASSEMBLIES (TB 55-1520-242-20-1) (UH-1-79-17)

1. SAFETY OF FLIGHT MESSAGE - ONE TIME INSPECTION OF UH-1 SERIES HELICOPTER TAIL ROTOR HUB ASSEMBLIES (TB 55-1520-242-20-1) (UH-1-79-17)

1. SUMMARY:

A. WHEN COMPLYING WITH THE REFERENCED MESSAGE IT WAS DISCOVERED THAT SOME TAIL ROTOR HUB DATA PLATES WERE ILLEGIBLE OR MISSING. TAIL ROTOR HUB ASSEMBLIES ARE NOT RECORDED ON DA FORM 2420-16.

B. THE PURPOSE OF THIS MESSAGE IS TO IDENTIFY TAIL ROTOR HUB ASSEMBLIES BY LISTING YOKE SERIAL NUMBERS.

2. PARAGRAPH 9A IS AMENDED TO READ AS FOLLOWS:

INSPECT TAIL ROTOR HUB ASSEMBLY DATA PLATE TO DETERMINE HUB ASSEMBLY SERIAL NUMBER.

3. PARAGRAPH 9B IS AMENDED TO READ AS FOLLOWS:

THE FOLLOWING SERIAL NUMBER TAIL ROTOR HUB ASSEMBLIES SHALL BE REMOVED FROM SERVICE AND DISPOSED OF IN ACCORDANCE WITH PARAGRAPH 7C1 ABA-52412, ABA-52443, ABA-52445, ABA-52447, ABA-52450

153

PAGE 3 RUKTFFC4953 UNCLAS E F T O

ABA-50468 AND ABA-50469,

NOTE: TAIL ROTOR HUB ASSEMBLIES WITH MISSING OR ILLEGIBLE ASSEMBLY DATA PLATES SHALL BE INSPECTED TO DETERMINE YOKE SERIAL NUMBERS, THE FOLLOWING YOKE SERIAL NUMBERS SHALL CORRESPOND TO THE HUB ASSEMBLIES LISTED ABOVE: A3-25274, A3-25322, A3-24974, A3-24483, A3-25331, A3-25351, AND A3-25244.

4, THIS MESSAGE DOES NOT GROUND AIRCRAFT THAT HAVE COMPLIED WITH THE REFERENCED MESSAGE.

5, IF CLARIFICATION OF THIS MESSAGE IS REQUIRED, CONTACT MR. RON DESPLINTER, AUTOVON 693-1351, COMMERCIAL 314-263-1351.

BT
#2279

VNNN

29 AUG 79 00 35z

(22)

ARMY

Mr.
Rau

UH-1-79-19
one time insp. of
T/R hub assy

OCTUZEXH RULNNAQ2279 2402254-UUUU--RUMNDA,
 ZNR UUUUU
 O P 281908Z AUG 79 ZEX
 FM MGR ARNG DAC EDGEWOOD AREA APS MD //NOB-AVN-L//
 TO +AIG 7401
 O P 281908Z AUG 79 ZFE-4
 FM ODR USATSARCOM SYL MD //ORSTS-MBA(2)//
 TO AIG 8881
 AIG 7513
 RUEDDQA/US ENV PROTECTION AGY REGION 11 26 FEDERAL PLAZA NY NY
 RUMNSSS/US ENV PROTECTION AGY PO BOX 15027 LAS VEGAS NV
 //OPC RSCH DEV ENV MONITORING AND SPT LAB/HOD//
 RUEBPAA/NATIONAL OCEANIC AND ATMOSPHERIC ADM ROCKVILLE MD
 //NOAA/OA2//
 INFO AIG 9884
 AIG 7514
 RUCLEUA/CDR USAAVNG FT RUCKER AL //ATZQ-DI//

BT
 UNCLAS E F T O
 N//OA2 FOR COL L A WEAVER
 NUCLEUA THIS IS A SAFETY OF FLIGHT MESSAGE AND HAS NOT, REPEAT
 HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES,
 ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL
 SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED,
 THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE,

PAGE 2 RUMTEFC4953 UNCLAS E F T O
 SUBJECT: CHANGE TO SAFETY OF FLIGHT MESSAGE - ONE TIME INSPECTION
 OF UH-1 SERIES HELICOPTER TAIL ROTOR HUB ASSEMBLIES (TB 55-1528-
 242-20-1) (UH-1-79-17)

A. SAFETY OF FLIGHT MESSAGE - ONE TIME INSPECTION OF UH-1 SERIES
 HELICOPTER TAIL ROTOR HUB ASSEMBLIES (TB 55-1528-242-20-1)
 (UH-1-79-17)

1. SUMMARY:
 A. WHEN COMPLYING WITH THE REFERENCED MESSAGE IT WAS
 DISCOVERED THAT SOME TAIL ROTOR HUB DATA PLATES WERE ILLEGIBLE OR
 MISSING, TAIL ROTOR HUB ASSEMBLIES ARE NOT RECORDED ON DA FORM
 2428-16.

B. THE PURPOSE OF THIS MESSAGE IS TO IDENTIFY TAIL ROTOR HUB
 ASSEMBLIES BY LISTING YOKE SERIAL NUMBERS.

2. PARAGRAPH 9A IS AMENDED TO READ AS FOLLOWS:
 INSPECT TAIL ROTOR HUB ASSEMBLY DATA PLATE TO DETERMINE HUB
 ASSEMBLY SERIAL NUMBER.

3. PARAGRAPH 9B IS AMENDED TO READ AS FOLLOWS:
 THE FOLLOWING SERIAL NUMBER TAIL ROTOR HUB ASSEMBLIES SHALL BE
 REMOVED FROM SERVICE AND DISPOSED OF IN ACCORDANCE WITH PARAGRAPH
 701 ABA-52412, ABA-52443, ABA-52445, ABA-52447, ABA-52458

(52)

PAGE 3 RUKTFFC4953 UNCLAS E F T O

ABA-50468 AND ABA-50469,

NOTE: TAIL ROTOR HUB ASSEMBLIES WITH MISSING OR ILLEGIBLE ASSEMBLY DATA PLATES SHALL BE INSPECTED TO DETERMINE YOKE SERIAL NUMBERS, THE FOLLOWING YOKE SERIAL NUMBERS SHALL CORRESPOND TO THE HUB ASSEMBLIES LISTED ABOVE: A3-25274, A3-25322, A3-24974, A3-24483, A3-25331, A3-25351, AND A3-25244.

4, THIS MESSAGE DOES NOT GROUND AIRCRAFT THAT HAVE COMPLIED WITH THE REFERENCED MESSAGE.

5, IF CLARIFICATION OF THIS MESSAGE IS REQUIRED, CONTACT MR. RON DESPLINTER, AUTOVON 693-1351, COMMERCIAL 314-263-1351.

BT

#2279

NNNN