

DUPLICATE

Good light sets
GEN-76-4

532

RATUZFDY RULNEAA0595 0281611 RUED-UUUU-RUWMDTA
RATUZEXW RULNEAA0595 0281611-UUUU-RUWMDTA
ZNR UUUUU

R 281607Z JAN 76 ZEX

FM ARNG OAD EDGEWOOD MD //OAC-AVN-L//

TO AIG 7401

INFO RUEFHQA/ONGB WASH DC //NGB-ARL-A//

R 272110Z JAN 76 ZFF-6

FM CDR USAAVSCOM STL MO //AMSAV-FEQ//

BT

UNCLAS

NOTE - THIS MESSAGE HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO
UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES ARE RESPONSIBLE
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED.
RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.

SUPJ OLN MAINTENANCE ADVISORY MESSAGE ON POTENTIAL SAFETY HAZARD,
CATEGORY 1, NSN 8230-00-299-5879 FLOODLIGHT SETS, CONTRACT DSA
400-75-0-4606, MANUFACTURER UNKNOWN, (GEN 76-4)

1. STOCK UNDER CONTRACT DSA 400-75-0-4606 HAS BEEN DECLARED
POTENTIALLY HAZARDOUS DUE TO INADEQUATE SPRING TENSION ON
OUTLET AND SWITCH COVERS LOCATED ON THE ELECTRICAL CONNECTOR
BOX.

PAGE 2 RULNEAA0595 UNCLAS

2. REQUEST ALL UNITS CONDUCT A SURVEILLANCE INSPECTION ON
FLOODLIGHTS PRODUCED UNDER CONTRACT DSA 400-75-0-4606 TO
DETERMINE IF WATER PENETRATION INTO THE ELECTRICAL COMPONENTS
MAY OCCUR. SUSPEND ALL DEFECTIVE UNITS FROM USE AND ISSUE
IMMEDIATELY AND INFORM DGSC OF THE QUANTITY OF DEFECTIVE UNITS
AND ACCEPTABLE UNITS ON HAND PRODUCED UNDER THIS CONTRACT.
3. IT IS FURTHER REQUESTED THAT FLOODLIGHT SETS PRODUCED UNDER
CONTRACT AF 33 (038) 16516 BE SUSPENDED FROM USE AND ISSUE
IMMEDIATELY. THESE LIGHTS POSSIBLY HAVE A TWO-WIRE SYSTEM IN
LIEU OF A THREE-WIRE. UNITS WITH THIS TYPE OF CONFIGURATION MAY
BE UNSAFE. PLEASE INFORM DGSC OF THE NUMBER OF FLOODLIGHTS
ON HAND PRODUCED UNDER THIS CONTRACT AND STATE WHETHER THEY
HAVE A TWO-WIRE OR THREE-WIRE SYSTEM.

4. FORWARD YOUR REPLY TO ABOVE REQUESTS BY COB 6 FEB 76 TO
CDR, DGSC, RICHMOND, VA, DGSC-606P4 021-9869 MR COOPER,
AUTOVON 695-3623. YOUR PROMPT ATTENTION TO THIS MATTER WILL
BE APPRECIATED.

BT

95

ARMY

29