

6 Jul 77 14 39

July 1977
Gen 77-15
Low reflective
lacquer

RAAUZBXW RULNNAQ2192 1871428-00000-RUNMDTA;

ZNR 00000

R 051458Z JUL 77 ZEX

FM CDR ARNG-OAS EDGEWOOD MD //ONGB-AVN-L//

TO AIG 7481

INFO RUEADHD/ONGB WASH DC //ONGB-ARL-A//

R 051428Z JUL 77 ZEX

FM CDR USATSAROOM STL MO //DRSTS-MEG//

TO AIG 8881

BT

UNCLAS

NOTE - THIS MESSAGE HAS NOT, REPEAT, HAS NOT BE TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES; ADDRESSEES ARE RESPONSIBLE FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED; RETRANSMITTAL SHALL REFERENCE THIS MESSAGE;

SUBJ - MAINTENANCE ADVISOR MESSAGE ON LACQUER, LOW REFLECTIVE; MILHL-46199, NSN 8210-20-283-6588 (GEN 77-15)

1. SUBJECT PAINT PRODUCED BY ENMAR INC., WICHIT KS, IN LOTS 76-89, 76-92 AND 76-91 HAVE BEEN FOUND TO BE FAILING THE SPECIFICATION REQUIREMENTS FOR CONDITION IN CONTAINER AND FOR FINENESS OF GRIND;

Army

PAGE 2 RULNNAQ2192 UNCLAS

2. THE PAINT IDENTIFIED IN PARA 1 SHALL BE WITHHELD FROM USE; QUALITY DEFICIENCY REPORT (SF-368) SHALL BE FORWARDED TO THE GSA SERVICING REGION WHERE THE MERCHANDISE AND CONSIGNEE ARE LOCATED;
3. THE ACTIONS IN PARA 2 SHALL BE PERFORMED AT THE EARLIEST POSSIBLE TIME TO PURGE THE DEFECTIVE PAINT FROM THE SYSTEM;
4. POINT OF CONTACT IN TSAROOM IS MR. J. W. DEAN; DROPH-ASE-LM; AUTOVON 698-6496 OR COMMERCIAL 314-268-6496;

BT

42192

18