

signal smoke  
illumination  
GEN-76-11

6 MAR 76 19 40Z

*ARMY*

RATUZELK RULNNAC2128 1271336-UUUU--RUMMDTA;  
ZNR UUUUU  
R 061336Z MAY 76 ZEX ZEL VOL GON  
FM ARNG-DAC EDGEWOOD MD  
TO AIG 7421  
R 052014Z MAY 76  
FM CDR USAAVSCOM STL MO//DRSAV-WL//  
TO AIG 8881  
INFO AIG 9824  
RUCLDDA/CDRUSAAAVNS FT BUCKER AL//IGAR-TA//  
(ATTN MAJ DURAND)  
RUCIAPB/CDRARMCOB ROCK ISLAND IL//DRBAR-QAS//

BT  
UNCLAS

NOTE THIS MESSAGE HAS NOT REPEAT, HAS NOT BEEN TRANSMITTED TO  
UNITS SUBORDINATE TO ADDRESSES; ADDRESSES ARE RESPONSIBLE  
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,  
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR  
CONCERNED; RETRANSMITTAL SHALL REFERENCE THIS MESSAGE;  
SUBJ MAINTENANCE ADVISORY AVIATION LIFE SUPPORT EQUIPMENT ON  
THE FUNCTIONAL STATUS OF SIGNAL SMOKE ILLUMINATION; MARINE  
AN=MK-13-MOD-2 (1370L275) (GEN 76-11)  
1. REFERENCE PRELIMINARY REPORT OF ARMCO MALFUNCTION THAT WAS  
SUBMITTED BY CDRUSASCH, FT, SHAFTER, HAWAII, AFZV-DI-MUS; MK-13  
FLARSS (LOTS NO, 28-MK-8367 AND 31-MK-8367 WERE SUSPENDED WITH

PAGE 2 RUMTFFA3122 UNCLAS

ISSUE OF THE MALFUNCTION REPORT THAT WAS SUBMITTED BY COL JACK  
O. FRSSENDEN, DIRECTOR OF INDUSTRIAL OPERATIONS, THE MALFUNCTION  
REPORT WAS SUBMITTED ON BASIS OF BURNS SUFFERED BY PERSONNEL ON  
THE FACE, BACK, AND ARMS AND SCRATCHES ON CORNER OF LEFT EYE;  
INDIVIDUAL WAS TREATED AND RELEASED; SUSPECTED FLARE LOTS WERE  
LOCALLY SUSPENDED AFTER ACCIDENT;

2. LISTINGS OF LOTS OF SUBJECT ITEMS ARE CONTAINED HEREIN FOR  
INFORMATION AND NECESSARY ACTION IN ACCORDANCE WITH SB 742-1;  
THE SB PROVIDES GUIDELINES FOR FUNCTION TESTS AND FUNCTIONAL TEST  
SAMPLES FOR THE SUBJECT ITEMS;

3. UNSERVICEABLE (FUNCTIONAL CODE D) QUANTITIES REFLECTED BY  
HISTORICAL TEST RECORDS MAINTAINED BY HQGS, UNITED STATES ARMY  
ARMAMENT COMMAND, ROCK ISLAND, IL 61281, ATTN MR, FINLEY,  
AUTOVON 793-4821, EXT 225, ARE LIMITED TO THOSE LOT/QUANTITIES  
SHOWN IN TB 9-1388-385 AND THE NAR LISTINGS FURNISHED TO ARMCOM  
BY THE NAVY SHIPS PARTS CONTROL CENTER. A RECAP OF THESE ITEMS/  
LOTS FOLLOWS

A. LOTS SUSPENDED BY TB 9-1388-385-1 AND -2  
(1) ALL LOTS OF API MANUFACTURER SYMBOL  
(2) 78-MK-8263

(63)

signal smoke  
illumination  
GEN-76-11

6 MAR 76 19 40Z

*ARMY*

RATUZELK RULNNAC2128 1271336-UUUU--RUMMDTA;  
ZNR UUUUU  
R 061336Z MAY 76 ZEX ZEL VOL CON  
FM ARNG-DAC EDGEWOOD MD  
TO AIG 7421  
R 052014Z MAY 76  
FM CDR USAAVSCOM STL MO//DRSAV-WL//  
TO AIG 8881  
INFO AIG 9824  
RUCLDQA/CDRUSAAAVNS FT BUCKER AL//IGAR-TA//  
(ATTN MAJ DURAND)  
RUCIAPB/CDRARMCOB ROCK ISLAND IL//DRBAR-QAS//

BT  
UNCLAS

NOTE THIS MESSAGE HAS NOT REPEAT, HAS NOT BEEN TRANSMITTED TO  
UNITS SUBORDINATE TO ADDRESSES; ADDRESSES ARE RESPONSIBLE  
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,  
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR  
CONCERNED; RETRANSMITTAL SHALL REFERENCE THIS MESSAGE;  
SUBJ MAINTENANCE ADVISORY AVIATION LIFE SUPPORT EQUIPMENT ON  
THE FUNCTIONAL STATUS OF SIGNAL SMOKE ILLUMINATION, MARINE  
AN=MK-13-MOD-2 (1370L275) (GEN 76-11)  
1. REFERENCE PRELIMINARY REPORT OF ARMCO MALFUNCTION THAT WAS  
SUBMITTED BY CDRUSASCH, FT, SHAFTER, HAWAII, AFZV-DI-MUS; MK-13  
FLARSS (LOTS NO, 28-MK-8367 AND 31-MK-8367 WERE SUSPENDED WITH

PAGE 2 RUMTFFA3122 UNCLAS

ISSUE OF THE MALFUNCTION REPORT THAT WAS SUBMITTED BY COL JACK  
O. FRESSDEN, DIRECTOR OF INDUSTRIAL OPERATIONS, THE MALFUNCTION  
REPORT WAS SUBMITTED ON BASIS OF BURNS SUFFERED BY PERSONNEL ON  
THE FACE, BACK, AND ARMS AND SCRATCHES ON CORNER OF LEFT EYE;  
INDIVIDUAL WAS TREATED AND RELEASED, SUSPECTED FLARE LOTS WERE  
LOCALLY SUSPENDED AFTER ACCIDENT.

2. LISTINGS OF LOTS OF SUBJECT ITEMS ARE CONTAINED HEREIN FOR  
INFORMATION AND NECESSARY ACTION IN ACCORDANCE WITH SB 742-1;  
THE SB PROVIDES GUIDELINES FOR FUNCTION TESTS AND FUNCTIONAL TEST  
SAMPLES FOR THE SUBJECT ITEMS.

3. UNSERVICEABLE (FUNCTIONAL CODE D) QUANTITIES REFLECTED BY  
HISTORICAL TEST RECORDS MAINTAINED BY HQGS, UNITED STATES ARMY  
ARMAMENT COMMAND, ROCK ISLAND, IL 61281, ATTN MR, FINLEY,  
AUTOVON 793-4821, EXT 225, ARE LIMITED TO THOSE LOT/QUANTITIES  
SHOWN IN TB 9-1388-385 AND THE NAR LISTINGS FURNISHED TO ARMCOM  
BY THE NAVY SHIPS PARTS CONTROL CENTER. A RECAP OF THESE ITEMS/  
LOTS FOLLOWS

A. LOTS SUSPENDED BY TB 9-1388-385-1 AND -2  
(1) ALL LOTS OF API MANUFACTURER SYMBOL  
(2) 78-MK-8263

(63)

T THE MANUFACTURE DATES SPECIFIED IN PARAGRAPH 3 SHOULD BE COMPARED TO  
THE MANUFACTURE DATES SPECIFIED IN PARAGRAPH 3B, ALL LOTS OF THE  
SIGNALS NOT LISTED BY PARAGRAPH 3 OR PARAGRAPH 4 SHOULD BE  
REPORTED TO HDQS, USA DARGOOM, DR SAR-GAS, ATTN: MR. FINLEY, ROCK  
ISLAND, IL 61201, AUTOVON 793-4021, EXT 225,  
6. ASSETS LISTED IN PART 6 OF WAR'S REPORT WILL NOT SUPPORT AN  
EXTENSIVE MAINTENANCE PROGRAM,

BT  
#2128

NNNN

19