

PRIORITY

DTUZEXN RULNET00196 11918MS-UUUU--RUMHDTA.

NR UUUUU

281335Z APR 80 ZEX

1 MGR ARNG OAC EDGEWOOD AREA APR MO //NOB-AVN-L//

3 AIG 7481

221809Z APR 80

1 CDRTSARCOM STL MO //DRSTS-MEA(2)//

3 AIG 8881

T

UNCLAS

OTE CLN THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT AS NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED, AS TRANSMITTAL SHALL REFERENCE THIS MESSAGE.

SUBJECT CLN MAINTENANCE ADVISORY MESSAGE, REPLACEMENT OF HYDRAULIC PRESSURE SWITCH PN 204-276-257-1 NSN 5938-02-646-3495, OH-1-80-06, SUBJECT PRESSURE SWITCH HAS AN UNACCEPTABLE FAILURE RATE, PENDING REVISION OF APPLICABLE TECHNICAL MANUALS, TM 55-1520-10-23 AND TM 55-1520-210-23\* ALL CONCERNED ARE AUTHORIZED ON ATTRITION BASIS TO REPLACE HYDRAULIC PRESSURE SWITCH, 204-276-257-1 NSN 5938-02-646-3495 WITH HYDRAULIC PRESSURE

*Message  
281335Z  
Apr 80*

*28 APR 80 19 28Z*

AGE 2 RULNET00196 UNCLAS

WITCH PN 88617, NSN 5938-02-939-7584,

THE FOLLOWING ADDITIONAL ITEMS ARE REQUIRED TO ACCOMPLISH REPLACEMENT.

WCKING, MS28778-4 NSN 5338-02-875-2096 1 EA

WCKING, MS28778-6 NSN 5338-02-874-9965 1 EA

EDUCER, MS2439782 NSN 5365-02-874-7915

STANDARD FORM 348 (EQUIPMENT IMPROVEMENT RECOMMENDATION)

MISSION IAW TM 38-750 IS NO LONGER REQUIRED ON HYDRAULIC

RESSURE SWITCH, PN 204-276-257-1 NSN 5938-02-646-3495,

FOREIGN MILITARY SALES (FMS) RECIPIENTS REQUIRING

ARIFICATION OF THIS MESSAGE SHOULD CONTACT TSARCOM,

ST5-10, CW3 BROOK WATKINS, PHONE COMMERCIAL 314-263-2186,

AUTOVON 893-2186.

IF CLARIFICATION OF THIS MESSAGE IS REQUIRED, CONTACT MR.

Y BOLAND TSARCOM, PHONE COMMERCIAL 314-263-8396, OR AUTOVON

83-8396.

T

3156

*UH-1-80-06*

*N*

BTUZEKX RULNNA01147 1132058=UUUU=RRUMMDTA

NR UUUUU

222000Z APR 80 ZEX

4 HQR ARNG OAD (EA) APO MD //NGB=AVN=LY/

*army*

3 AIG 7401

221600Z APR 80

4 ODRTSARCOM STL MD //DRSTS=MEA(2)///

3 AIG 8881

IG 7515

JEBBEA/NATIONAL OCEANIC AND ATMOSPHERIC ADM //

DOCKVILLE MD/NOAA/ABB COL LIA WEAVER//

YPO AIG 9004

IG 7514

JOLEUA/CDRUSAAYNO FT RUCKER AL//ATZQ=QI//

JOMAD/OSDAO TEL AVIV ISRAEL

JFLAPA/OJUSMG=MAAD MADRID SPAIN //ARMY/NAV SEC//

JEMIN/AIT TAIPEI TAINAN

JEMO/AIT WASH DC

UNCLAS

DEI THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT

AS NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.

ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL

RELEVANT UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED.

ALL TRANSMITTALS SHALL REFERENCE THIS MESSAGE.

SUBJECT: MAINTENANCE ADVISORY MESSAGE, REPLACEMENT OF HYDRAULIC

AGE 02 RUCIFRA6194 UNCLAS

PRESSURE SWITCH PN 204-076-057-1 NSN 5930-00-646-3495; ~~UNRECORDED~~

SUBJECT PRESSURE SWITCH HAS AN UNACCEPTABLE FAILURE RATE.

PENDING REVISION OF APPLICABLE TECHNICAL MANUALS, TM 55-1320-

12-23 AND TM 55-1520-210-230 ALL CONCERNED ARE AUTHORIZED ON

AN ATTRITION BASIS TO REPLACE HYDRAULIC PRESSURE SWITCH.

PN 204-076-057-1 NSN 5930-00-646-3495 WITH HYDRAULIC PRESSURE

SWITCH PN 88617, NSN 5930-00-939-7584.

THE FOLLOWING ADDITIONAL ITEMS ARE REQUIRED TO ACCOMPLISH

REPLACEMENT:

PACKING, MS28778-4 NSN 5332-00-809-2966 1 EA.

PACKING MS28778-3 NSN 5332-00-809-2969 1 EA.

REDUCER, MS2439702 NSN 5365-00-809-7919.

STANDARD FORM 368 (EQUIPMENT IMPROVEMENT RECOMMENDATION)

MISSION IAW TM 38-750 IS NO LONGER REQUIRED ON HYDRAULIC

PRESSURE SWITCH, PN 204-076-057-1 NSN 5930-00-646-3495.

FOREIGN MILITARY SALES (FMS) RECIPIENTS REQUIRING

CLARIFICATION OF THIS MESSAGE SHOULD CONTACT TSARCOM,

STSLIC, CWS BROCK WATKINS, PHONE COMMERCIAL 324-263-2106,

OVON 693-2106.

CLARIFICATION OF THIS MESSAGE IS REQUIRED, CONTACT MR.

22 APR 80 21 42Z

03 RUCIFRA6194 UNCLAS