

CHECK FOR CAUSES OF FOD

The increased output of the new T53-L13 engine in the HueyCobra and "H" Model means an increased velocity air flow—thru the same diameter air inlet as on earlier engines.

So, you can see that FOD is even more critical on this baby. No matter what Huey you crew, tho, one of your most important maintenance checks is to eye the engine inlet area before and after every mission.

