UH-1-77-20
Return unserviceable engines to corpus
ARMY

RAAUZEXN RULNNAC4143 2922422-UUUU--RUNMOTA;
ZNR UUUUU
R 222422Z OCT 77 ZEX
FM CDR ARNG-OAC EDGEWOOD MD //NGB-AVN-L//
TO AIG 7421
INFO RUEAUSA/CNGB WASH DC //NGB-ARL-A//
R 211512Z OCT 77
FM CDR USATSARCOM STL MO //DRSTS-MEP(2)//
TO AIG 8881
INFO AIG 8204
BT
UNCLAS
NOTE - THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT BEEN
TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD
RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR
ELEMENTS CONCERNED. THE RETRANSMITAL SHALL REFERENCE THIS MESSAGE.
SUBJ - MAINTANANCE ADVISORY MSG CONCERNING THE RETURN OF UNSERVICEA-
ABLE T53-L-13B, 15 AND 701A ENGINES. (UH-1-77-20), (AH-1-77-21) AND
(OV-1-77-7).
1. THE PURPOSE OF THIS MESSAGE IS TO REQUEST ALL UNSERVICEA LE
SELECT ENGINES NOT REPAIRABLE AT AVIM, INCLUDING EIR ENGINES, BE
RETURNED TO CORPUS CHRISTI ARMY DEPOT ON AN EXPEDITED BASIS WITHOUT

PAGE 2 RULNNAC4143 UNCLAS
WAITING FOR DISPOSITION INSTRUCTION. A COPY OF THE EIR SHOULD BE
INCLUDED WITH APPROPRIATE ENGINE DOCUMENTATION.
2. INCREASED OVERHAUL USAGE OF POWER TURBINE ROTOR DISC P/N
1-143-272-21 HAS CAUSED A CRITICAL SUPPLY SHORTAGE AND COAD WILL BE
UTILIZING ROBBACK IN ORDER TO PREVENT SHUT DOWN OF THE T53 ENGINE
OVERHAUL LINE. MAY ENGINES ARE NOT BEING RETURNED FROM THE FIELD
SINCE THEY ARE AWAITING DISPOSITION INSTRUCTIONS AS A RESULT OF THE
EIR PROGRAM.
3. THIS ACTION IS REQUIRED TO ASSURE AVAILABILITY OF ENGINES FOR
INDUCTION TO THE OVERHAUL PROGRAM AND ASSURE LOGISTIC SUPPORT FOR
THE AIRCRAFT SYSTEMS.
4. IF ADDITIONAL INFORMATION OR CLARIFICATION IS REQUIRED, PLEASE
CONTACT FRANK STEVENS, AUTOVON 693-5207, COMMERCIAL 314-263-5207.
BT
#4143

22 OCT 77 06 03