18 Dec 75 21 192

Defective epoxy primer
Gen -75-36

ARMY

ATTUZEŘW RUĹNĞĂĂĪ039 352ĪŏĪ6-UUUU--RUWHDTĂ.
ZNR UUUUU
R 181915Z DEC 75
FM ARNG OPERATING ACTIVITY CENTER//OAO-AVN-L//
TO AIG 7401
INFO ONGB WASH DC//NGB-ARL-A//
R 171958Z DEC 75 ZEX ZEZ
FM COR USAAVSCOM STL MO//AMSAV-PRQ//
TO AIG 8881
BT
UNCLAS
NOTE OLN THIS MESSAGE HAS NOT OMM REPEAT OMM HAS NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES ARE RESPONSIBLE FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OMM ELEMENTS OMM OR FOREIGN USERS AFFECTED OR CONCERNED. RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.
SUBJ OLN MAINTENANCE ADVISORY MESSAGE ON DEFECTIVE EPOXY PRIMER //MIL-P-23377/ /GEN-75-36/
A. GSA MRQ RIOI6402 DEC 75 OMM SUBJ OLN DEFECTIVE PRIMER COATING.
FOLLOWING NSN/BATCHES OF PRIMER COATING SUPPLIED BY CORONADO [illegible] CO. ARE DEFECTIVE. MATERIAL IS HARDENED AND WILL NOT MIX PROPERLY OLN

PAGE 2 RUĹNĞĂĂĪ039 UNCLAS

| NSN | BATCH | GSA CONTRACT |
|---|---|---|
| 8010-00-782-2450 | 122 | GS-105-37935 |
| 8010-00-782-2450 | 186 | GS-105-37818 |
| 8010-00-782-2450 | 123 | GS-105-37538 |
| 8010-00-782-2450 | 261 | GS-105-37975 |
| 8010-00-782-2450 | 395 | GS-105-35782 |
| 8010-00-782-2477 | 175 | GS-105-37975 |
| 8010-00-782-7080 | 997 | GS-105-37326 |
| 8010-00-935-7080 | 992 | GS-105-37935 |

6-N-5

PLACE ALL STOCK OF THESE ITEMS IN HOLD PENDING DISPOSITION INSTRUCTION FROM GSA. REPORT STOCK OF ABOVE NSN/BATCH/CONTRACT TO GSA SHIPPING REGION INCLUDING ORIGINAL RQN NUMBEROMM ON SF 368 /MILITARY/ OR SF 364 /CIVILIAN/. DEADLINE FOR REPORTING MARCH 1 OMM 1976.
BT
81036

24

IN STOCK ITEMS DID NOT Reflected ANY of above contracts or Batch # MAB. 19Dec75

29