




Dear Editor,

The UH-1 sliders take a real beating, guiding the cargo doors. As a result, the plastic wears out and the slider (costing dollars) has to be replaced.

Well, we figured out a way to just replace the plastic inserts at a cost of only pennies.

It's just a matter of removing the worn plastic and replacing it with bearing strip, NSN 1560-00-448-5799. The strip is glued in place.



This is one way to beat the high cost of repair parts.

*Raymond J. Bachmeier
Nevada Army National Guard*

(Ed Note—Good idea. The head hangar—TSARCOM—is adding your bearing strip to Figs 47 and 48 of TM 55-1520-210-23P.)