

...IT'S WHAT??"



Tinkle, tinkle little spar...how I wonder what you are?  
Wonder no longer, Hueymechs. That sound of tinsel inside the UH-1 tail rotor blade is normal.

It just so happens that during manufacture the aluminum honeycomb at the blade tip is drilled to allow for installation of the balance weights

Sometimes all the residue can't be removed.

A little tinkle is no wrinkle. Keep the blade.