




The nipple, NSN 5975-00-553-6995, on the chip detector of a Huey intermediate or tail rotor gear box, slips down the electrical wire, exposing the connection to the weather.



The big end of the nipple is not large enough to fit over the chip detector knurl, which would hold it in place.



So what's the solution? Try this for size:

- 1 Latch on to hand tool, NSN 5120-00-781-7891 or 5120-00-937-5438, and plastic tiedown strap, NSN 5975-00-074-2072.

