

20 Jan 76  
epoxy primer  
GEN 76-03

RATUZEXW RULNEAA0596 0201001-0000--RUWMDTA;  
ZNR UUUUU

~~0201001Z JAN 76 ZEX~~

FM ARNG OAC EDGEWOOD MD //OAC-AVN-L//  
TO AIG 7401

INFO RUEFHQA/CNGB WASH DC //NGB-ARL-PA//

R 272140Z JAN 76

FM CDR USAAVS00M STL MD //AMSAV-FEG//

BT  
UNCLAS

NOTE CLN THIS MESSAGE HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO  
UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES ARE RESPONSIBLE  
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,  
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED.  
RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.  
SUBJ CLN MAINTENANCE ADVISORY MESSAGE ON DEFECTIVE EPOXY

- 1. PRIMER (MIL-PR-23377) (GEN 76-03)
- 2. OUR MESSAGE 171930Z DEC 75 (GEN 75-06)
- 3. GSA MESSAGE 501230Z DEC 75
- 4. VENDOR ATTEMPTING TO PICK UP DEFECTIVE EPOXY PRIMER FROM ALL
- 5. SPOCS FOR REMIXING. ACTIVITIES CONUS HOLD DEFECTIVE MATERIAL
- UNCL CONTACTED BY GSA REGION. ALL ACTIVITIES NOT LOCATED CONUS.

ARMY

PAGE 2 RULNEAA0596 UNCLAS  
DISPOSE OF DEFECTIVE MATERIAL IAW LOCAL INSTRUCTIONS;  
2. POINT OF CONTACT, JOHN C. TRESELER, DIR., ORDER PROCESSING &  
CONT. DIV, GSA, WASH, DC, REFER TO FPO 206, AREA CODE 703-557-1707;  
BT

0596  
10  
3

None on Hand

NNNN