


## A NEW SEALANT



Hueys coming off the production line now have Sealing Compound, MIL-S-8802, applied around the edge of the 90° gear box. It does a good job of keeping moisture from getting in between the gear box and mount.

The pubs are being updated to require use of the sealant, after mounting the gear box. NSN 8030-00-753-5006 will get you a 2½-oz tube of sealant, item 207, Table 1-2 of TM 55-