

POTUZEXH RULNET0396 2661805=UUUU=RUHMDTA;
ZNR UUUUU

P 221430Z SEP 80 ZEX

FM MGR ARNG DAC EDGEWOOD MD //NGS=AVN=C//

TO AIG 7401

RUHMOMA/AAFA JUNEAU AK

RULNNHG/MAOE HAVRE DE GRACE MD

BT

UNCLAS

SUBJ COMPLIANCE WITH MWO 55-1500-219-30-9

A, MWO 55-1500-219-30-9, INSTALLATION OF MAIN ROTOR MAST INSERT
PLUG, 3, AUG 78;

B, LTR, HODA DALO=AV, DTD 12 SEP 80, SAB (NOTAL)

1, REF A REQUIRES COMPLIANCE PRIOR TO 1 OCT 80, HOWEVER, CDRTSARCOM
INDICATES THAT NO ADDITIONAL MWO KITS ARE AVAILABLE, COMPLIANCE
WILL NOW REQUIRE THE ACQUISITION AND INSTALLATION OF THICK WALL
MAST PN 204-040-360-15, AS THIS MAST IS NOT USABLE ON THE UH-1 O/M,
SUFFICIENT MODIFIED UH-1 B/D/M WILL REQUIRE NEW MASTS IN ORDER TO
PROVIDE MAST PLUGS TO MODIFY THE UH-1 O/M;

2, TO RESOLVE THIS PROBLEM THIS OFFICE HAS:

A, REQUESTED AN EXTENSION ON THE COMPLIANCE DATE, REQUESTS
FROM EACH FACILITY ARE NOT NECESSARY;

PAGE 2 RULNET0396 UNCLAS

B, PROVIDED FY80 FUNDING TO THE OUSPPD OF EACH AVORAD STATE
TO COVER COSTS OF THE THICK WALL MASTS;

C, TRANSMITTED CURRENT TSARCOM MWO STATUS TO THE AVORAD'S;

3, THE AVORAD'S WILL:

A, UPDATE THE CURRENT MWO STATUS AND REQUEST REQUISITION NOS
FOR THOSE MASTS ALREADY REQUESTED BY THE FACILITY;

B, REQUISITION SUFFICIENT MASTS TO COMPLETE THE UH-1 B/D/M
MODIFICATION AND FREE MAST PLUGS FOR THE UH-1 O/M, REQ WILL NOT
BE REQUIRED BY IND STATES;

C, PROVIDE REDISTRIBUTION INSTRUCTIONS FOR THE REMOVED MAST
PLUGS AND SUBSEQUENT INSTALLATION IN THE UH-1 O/M;

3, AASF/AAFA SHOULD:

A, PROVIDE CURRENT MWO AND REQUISITION STATUS TO THE AVORAD
UPON RECEIPT OF THIS MESSAGE, NOTE, STATUS SHOULD BE PROVIDED BY
PHONE ASAP BUT NLT 24 SEP 80;

B, INSTALL MAST UPON RECEIPT;

C, PROVIDE A WEEKLY UPDATE STATUS TO SUPPORTING AVORAD UNTIL
ALL MASTS ARE INSTALLED;

D, RESPOND TO THE MAST PLUG REDISTRIBUTION INSTRUCTION OF THE
AVORAD'S

— Army R.H.