


Hydraulic Filter Confusion



Replacing the filter element of your Huey's hydraulic filter assembly can leave you scratching your head, especially if you don't heed the NOTE in Para 7-48a(12) of TM 55-1520-210-23-2.

That's because there are three similar—but different—filter assemblies in use under the same stock number, NSN 1650-00-457-9844. Most of the same components are in each assembly, but not all of them. That's where the confusion crops up. In addition, the stackup of identical components is slightly different among the three models.

If you have to replace a filter element or other component in your bird's filter assembly, use the following chart:

