

WESTERN UNION C.R.C.  
MCLB DRAWER 38  
ALBANY GA 31704 22AM

WESTERN UNION MAILGRAM



1-006402A295 10/22/91 ICS DODCRSE ABN BESA  
01448 DOD CRC ALBANY GA 221858Z OCT 91/295

USDA FOREST SERVICE  
3905 VISTA AVE  
BOISE ID 83705

*servo TBO*  
*AH-1*  
*UH-1M*  
*UH-1-92-ASAM-01*

1 R RUCIFRD5340 2951750 DA-BDCVBA  
R 221300Z OCT 91 ZEX  
FM CDRAVSCOM ST LOUIS MO //AMSAV-XSOF//  
TO RUCLRFA/USDA FOREST SERVICE AVIATION FIRE MGMT  
//3905 VISTA AVE BOISE ID 83705//  
DA-BDCVBA  
PAGE 02 RUCIFRD5340 UNCLAS

UNCLAS  
SECTION 01 OF 02  
SUBJECT - AVIATION SAFETY ACTION MESSAGE, MAINTENANCE MANDATORY,  
RCS CSGLD-1860(R1), ALL AH-1 SERIES AIRCRAFT AND UH-1M AIRCRAFT,  
REVISION TO THE RE-ESTABLISHMENT OF A NEW TRACKING OF TIME BETWEEN  
OVERHAUL FOR THE SERVO CYLINDER ASSEMBLY, NSN 1650-01-016-3572,  
(AH-1-92-ASAM-01) (UH-1-92-ASAM-01) (TB 55-1520-243-20-18)  
NOTE - THIS IS AN AVIATION SAFETY ACTION MESSAGE AND HAS NOT BEEN  
TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD  
IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS,  
ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED. THE RETRANSMITTAL  
SHALL REFERENCE THE MESSAGE. ACTION ADDRESSES WILL IMMEDIATELY  
VERIFY THIS RETRANSMISSION TO COMMANDER, AVSCOM, ATTN - AMSAV-XSOF  
(SOF COMPLIANCE OFFICER).

1. PRIORITY CLASSIFICATION -
  - A. AIRCRAFT IN USE - NO CHANGE FROM (AH-1-ASAM-91-17)  
(UH-1-ASAM-91-18).
  - B. AIRCRAFT IN DEPOT MAINTENANCE - NO CHANGE FROM  
(AH-1-ASAM-91-17) (UH-1-ASAM-91-18).
  - C. AIRCRAFT UNDERGOING MAINTENANCE - NO CHANGE FROM  
PAGE 03 RUCIFRD5340 UNCLAS  
(AH-1-ASAM-91-17) (UH-1-ASAM-91-18)
  - D. AIRCRAFT IN TRANSIT -
    - (1) SURFACE/AIR SHIPMENT - WITHIN 90 DAYS OF ARRIVAL.
    - (2) FERRY STATUS - NO CHANGE FROM (AH-1-ASAM-91-17)  
(UH-1-ASAM-91-18).
  - E. MAINTENANCE TRAINERS (CATEGORY A, B AND OTHERS) - NO CHANGE  
FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).
  - F. COMPONENT/PARTS IN STOCK INCLUDING WAR RESERVES AT ALL  
LEVELS (DEPOT AND OTHERS) - UPON RECEIPT OF THIS MESSAGE ALL ITEMS  
LISTED IN PARAGRAPHS 6 AND 7 BELOW SHALL BE PLACED IN CONDITION  
CODE //J// AND RETAGGED WITH A MATERIEL CONDITION TAG/LABEL -  
SUSPENDED (BROWN TAG) DD FORM 1575 OR LABEL DD FORM 1575-1. THE

WESTERN  
UNION MAILGRAM

②

REMARKS BLOCK MUST REFERENCE INSPECTION REQUIRED PER THIS MESSAGE (TB 55-1520-243-20-18). UPON COMPLETION OF THE REQUIRED INSPECTION, ITEMS WILL BE RETAGGED EITHER SERVICEABLE (YELLOW TAG) DD FORM 1574 OR UNSERVICEABLE/REPARABLE (GREEN TAG) DD FORM 1577-2 DEPENDENT UPON THE RESULTS. IF NOT COMPLIED WITH, THESE COMPONENTS/PARTS SHALL NOT BE ISSUED.

2. TASK/INSPECTION SUSPENSE DATE - WITHIN 90 DAYS FROM THE DATE OF THE ORIGINAL MESSAGE OR 30 DECEMBER 1991.

PAGE 04 RUCIFRD5340 UNCLAS

3. REPORTING SUSPENSE DATE - NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

4. SUMMARY OF PROBLEM - THE PURPOSE OF THIS MESSAGE IS TO UPDATE THE ORIGINAL MESSAGE AND CHANGE THE TASK/ INSPECTION SUSPENSE DATE FROM 25HRS/10 DAYS TO 90 DAYS FROM THE DATE OF THE ORIGINAL MESSAGE OR 30 DECEMBER 1991.

5. END ITEMS TO BE INSPECTED - NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

6. ASSEMBLY COMPONENTS TO BE INSPECTED - NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

7. PARTS TO BE INSPECTED - NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

8. INSPECTION PROCEDURES - NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

9. CORRECTION PROCEDURES -

A. NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

B. NO CHANGE FROM (AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

C. INITIATE A DA FORM 2410 COPY 2 WITH A "U" GAIN FOR THE SERVO CYLINDER ASSEMBLY P/N 204-076-511-9, NSN 1650-01-016-3572 AND A DA FORM 2410 COPY 3 TO SHOW ON WHICH AIRCRAFT THE SERVO CYLINDER

PAGE 05 RUCIFRD5340 UNCLAS IS INSTALLED. IF THE SERVO CYLINDER ASSEMBLY HAS A (WOMJAA) SERIAL NUMBER ASSIGNED FROM CORPUS CHRISTI ARMY DEPOT, COMPLY WITH INSTRUCTIONS OF DA PAMPHLET 738-751 FUNCTIONAL USERS MANUAL FOR THE ARMY MAINTENANCE MANAGEMENT SYSTEMS-AVIATION (TAMMS-A), DATED 15 JAN 88, PAGE 14, PARAGRAPH 2-23 FOR NATIONAL STOCK NUMBER CHANGES (DA FORM 2410) AND PARAGRAPH 9D BELOW. ALTHOUGH THE 738-751 GIVES INSTRUCTIONS FOR (NSN) CHANGES, THESE INSTRUCTIONS CAN BE APPLIED FOR SERIAL NUMBER CHANGES AS NEEDED.

D. OBTAIN A NEW SERIAL NUMBER FROM THE SERIAL NUMBER ASSIGNMENT PROGRAM (SNAP) OFFICE, AMSAV-MPPD, DSN 693-2900/2901, STAMP THE NEW SERIAL NUMBER ON ONE OF THE BANDS LISTED BELOW

APPROXIMATE SIZE	NSN	P/N
5" X 1"	9905-00-060-2034	100-024-1

14:10 EST

MGMCOMP

WESTERN UNION C.R.C.  
MCLB DRAWER 38  
ALBANY GA 31704 22AM

WESTERN UNION MAILGRAM



1-006410A295 10/22/91 ICS DODCRSD ABN BESS  
01451 DOD CRC ALBANY GA 221859Z OCT 91/295

3

USDA FOREST SERVICE AVIATION  
3905 VISTA AVE ATTN FIRE MGMT  
BOISE ID 83705

1 R RUCIFRD5341 2951750 DA-BDCVBA  
R 221300Z OCT 91 ZEX  
FM CDRAVSCOM ST LOUIS MO //AMSAV-XSOF//  
TO RUCLRFA/USDA FOREST SERVICE AVIATION FIRE MGMT  
//3905 VISTA AVE BOISE ID 83705//  
DA-BDCVBA  
PAGE 02 RUCIFRD5341 UNCLAS  
UNCLAS

FINAL SECTION OF 02

1 1/2" X 3/4"	9905-00-060-2034	41001155
2 1/4" X 1 1/2"	9905-00-332-2497	MS 27253-1

OR MANUFACTURE THE BAND LOCALLY FROM TIIN ALUMINUM STOCK, AND  
CONTOUR THE NEW BAND TO MATCH THE CONTOUR OF THE CYLINDER.

INSTALL THE BAND ON THE SERVO CYLINDER ASSEMBLY P/N 204-076-511-9,  
NSN 1615-01-016-3572 ATTACH THE NEW BAND APPROXIMATELY IN THE SAME  
LOCATION AS THE OLD BAND USING ADHESIVE, EPI SEALANT SPECIFICATION  
2020, NSN 8040-00-738-6429, OR EA9309.3NA, NSN 8040-01-163-3481.

10. SUPPLY/PARTS AND DISPOSITION - NO CHANGE FROM

(AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

11. SPECIAL TOOLS, JIGS AND FIXTURES REQUIRED - NO CHANGE FROM

(AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

12. APPLICATION - NO CHANGE FROM (AH-1-ASAM-91-17)

(UH-1-ASAM-91-18).

13. REFERENCES - AVIATION SAFETY ACTION MESSAGE, MAINTENANCE  
MANDATORY, (AH-1-91-ASAM-17) (UH-1-91-ASAM-18) (TB 55-1520-243-20-16)

14. RECORDING AND REPORTING REQUIREMENTS - NO CHANGE FROM

(AH-1-ASAM-91-17) (UH-1-ASAM-91-18).

PAGE 03 RUCIFRD5341 UNCLAS

15. WEIGHT AND BALANCE - N/A.

16. POINTS OF CONTACT -

A. TECHNICAL POINT OF CONTACT FOR THIS MESSAGE IS

AH-1 MR. FRANK BARHORST, AMSAV-EIH, DSN 693-1624 OR COMMERCIAL  
314/263-1624.

UH-1M MR. FRED KERSHAW, AMSAV-ECH, DSN 693-1683 OR COMMERCIAL  
314-263-1683.

B. LOGISTICAL POINT OF CONTACT FOR THIS MESSAGE IS

AH-1 MR. JOE DEWITT, AMCPM-CO-L, DSN 693-1550 OR COMMERCIAL  
314/263-1550.

UH-1M MR. CHARLIE ELKINS/BOB INMAN, DSN 693-3763 OR COMMERCIAL  
314/263-3763.

To reply by Mailgram Message, see reverse side for Western Union's toll-free numbers.