

UH-1, AH-1 Series . . .

## Old and New Don't Mix


IT LOOKS LIKE  
YOU AND I COULD WORK  
TOGETHER!

I'M SORRY, BUT  
YOU'RE A LITTLE  
TOO OLD!

If you have to replace an air filter half, remember that the old and new filter halves don't mix.

Fig 107 of TM 55-1520-210-23P-1 gives NSN 2945-00-442-2539 for the lower half and 2945-00-442-2544 for the upper.

Those are the new-style filter halves. The parts manual says they replace the older models, NSN's 2945-00-917-7073 and -7074.



UH-1 . . .

But the old and new types don't work together. So if you still have the old kind, stay with them until stocks are exhausted. Then ask for the others.

Of course, you won't order both halves—old or new—if you only need to replace one part.