

PAUZEKX RULNNAQ4361 3882347-UUUU--RUWMDTA;  
ZNR UUUUU  
P 042348Z NOV 77 ZEX  
FM CDR ARNG-CAC EDGEWOOD MD//NGB-AVN-L//  
TO AIG 7481  
INFO RUSAUSA/CNGB WASH DC//NGB-ARL-A//  
P R 032848Z NOV 77  
FM CDRTSARCOM STL MO//DRSTS-NEU//

UH-1-77-21  
RSP9001-1 Trunnion  
bearings

Army  
30.

BT  
UNCLAS  
NOTE CLN THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT  
HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES,  
ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL  
SUBORDINATE UNITS ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED;  
THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.  
SUBJ CLN MAINTENANCE ADVISORY MESSAGE ON UH-1B/D/H HELICOPTERS  
REGARDING SNASHPLATE TRUNNION BEARING KSP9881-1 R -3 R -5  
K(UH-1-77-21)  
1. PURPOSE OF MSG CLN TO INFORM USERS THAT KSP9881-3OR -5 TRUNNION  
BEARINGS WITH ONE OR BOTH SNUBBERS BROKEN OFF MAY BE TREATED AS A  
K 881-1 TRUNNION, THE MAJOR DIFFERENCE BETWEEN THE KSP9881-1  
TRUNNION AND KSP9881-3 OR -5 TRUNNION IS THE ADDITION OF TWO SMALL

4 Nov 77 04 45 G

PAGE TWO RULNNAQ4362 UNCLAS  
PLASTIC SNUBBERS ON THE KSP9881-1 OR -5 TRUNNIONS WHICH RESTRICT  
MOVEMENT OF THE BALL IN ONE PLANE OF MOTION, THE PURPOSE OF THE  
SNUBBER IS TO AID IN THE CORRECT POSITIONING OF THE CYCLIC AND  
COLLECTIVE SERVO CYLINDERS DURING TRUNNION OR SERVO CYLINDER INSTAL-  
LATION OR MAINTENANCE, MISSING SNUBBERS DO NOT AFFECT THE  
SERVICABILITY OF THE TRUNNIONS,  
2. REPLACEMENT SNUBBERS WILL BE AVAILABLE FROM THE KSUPPLY SYSTEM  
UNDER NSN 1615-21826-8349, IN LATE DECEMBER 1977, FOR SUPPLY  
INFORMATION CONTACT MIKE MOORE, AUTOVON 698-2227, HOWEVER, UNTIL  
THEN, SNUBBERS MAY BE OBTAINED AS SALVAGE FROM UNSERVICABLE  
TRUNNIONS,  
3. POINT OF CONTACT AT THIS COMMAND IS FORREST HELZER, AUTOVON  
698-3914,  
BT  
#4361

13