

*Gen-77-1
defective fuel
cell sealant*

ARMY

RAAUZEXN RULNNAC0065 0070933-0000--RUHMDTA;
ZNR 00000
R 070933Z JAN 77
FM ARNG OAD EDGEWOOD ARSENAL MD//NGB-AVN-L//
TO AIG 7401
INFO RUEPHQA//NGB-ARL-A//
R 062000Z JAN 77 ZEX
FM ODR USAAVSCOM STL MD //DRSAV-FEG//
TO AIG 8881

BT
UNCLAS
NOTE CLN THIS MESSAGE HAS NOT, REPEAT HAS NOT, BEEN TRANSMITTED TO
UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES ARE RESPONSIBLE FOR
DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES,
ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED; RETRANSMITTAL
SHALL REFERENCE THIS MESSAGE;
SUBJ CLN MAINTENANCE ADVISORY MESSAGE ON DEFECTIVE FUEL CELL
SEALANT (GEN 77-1)
1. MSG, GKRA, R201732Z DEC 76, SUBJECT CLN DEFECTIVE FUEL CELL
SEALANT;
2. MSG, GSA, R131600Z DEC 76, SUBJECT CLN DEFECTIVE FUEL CELL
SEALANT;

261 91 1 7 78 192

PAGE 2 RULNNAC0065 UNCLAS
1. SEALANT, NSN 9030-00-753-5004, MFR ODAST PRO-SEAL, COMPTON;
CA, BATCH Q615164, SPEC MIL-6-8002D, PO NO, KW-13120-3, WAS FOUND
NOT SUITABLE FOR USE;
2. USERS MUST NOTIFY GSA, KANSAS CITY IMMEDIATELY ON SF 368 OR
MESSAGE SHOWING QUANTITY OF DEFECTIVE SEALANT, REFER TO GSA
FFCO 183;
3. GSA MUST NOTIFY CONTRACTOR NLT 30 DAYS;
4. HOLD DEFECTIVE SEALANT PENDING DISPOSITION INSTRUCTIONS;
BT
#0065

16

NNNN