



The Huey and Cobra tail rotor silent chain is kickin' up a ruckus, birdmen, so inspect the chain for cracks more often.

Ch 25 (May 76) to TM 55-1520-210-20 now calls for a close look at the installed chain every 10 flight hours. Use a suitable light, with at least a 3-power magnifying glass. This is a special check that you don't do at the same time as the preventive maintenance services (PMS) inspections.

'Course, the PMS cards call for the removal and inspection of all silent chains for cracks every Periodic. If your bird has a dark chain, P/N 205-001-721-1, NSN 1615-00-172-4508 (made before July 1974) it also gets the big look every 2nd Intermediate inspection.

Hang in there, mechs, with those special and PMS checks!

CHECK HERE, CAREFULLY, FOR CRACKS. USE A 3-POWER MAGNIFYING GLASS

