

UH-1-08-AMAM-01 Hoist

UNCLASSIFIED

MSG DTG 291400Z JAN 08

FROM COMMANDER, AMCOM, REDSTONE ARSENAL, AL //AMSAM-SF-A//

SUBJECT - AVIATION MAINTENANCE ACTION MESSAGE (AMAM), MAINTENANCE MANDATORY, RCS CSGLD-1860(R1), ALL H-60/UH-1 AIRCRAFT, GOODRICH INTERNAL RESCUE HOISTS, H-60-08-AMAM-05/UH-1-08-AMAM-01

.....NOTE.....
....This message is effective until rescinded or superseded.

.....NOTE.....
....This message is issued IAW AR 750-6 and has not been transmitted to units subordinate to addressees. Addressees will immediately retransmit this message to all subordinate units, activities or elements affected or concerned. Commanders of ACs, ARNG, USAR, ASCCs, and DRUs will immediately verify this retransmittal to the AMCOM SOF Compliance Officer (AMSAM-SF-A, safeadm@conus.army.mil).

.....NOTE.....
....Commanders of ACs, ARNG, USAR, ASCCs, and DRUs may authorize temporary exception from message requirements IAW AR 750-6, para 2-9. Exception may only occur when combat operations or matter of life or death in civil disasters or other emergencies are so urgent that they override the consequences of continued aircraft operation.

.....NOTE.....
....Commanders unable to comply with the requirements of this message within the time frame specified will change the affected aircraft status symbol to a Red //X//.

.....NOTE.....
....A listing of published safety messages, to include TAMMS Reports, Inspection Reports, and any Supplements/Addendums required by this message can be viewed/downloaded at: "https://asmprd.redstone.army.mil". This is a secure website which requires an Army Knowledge Online (AKO) ("www.us.army.mil") ID and password.

1. SUMMARY -

1.1. Background - Internal Hoists (PN 42305-3) are currently managed by another Service. In order to provide better, more structured and timely support to Army users, the decision has been made, with coordination of the hoist manufacturer, to convert specific PN 42305-3 hoists to PN 42305-5, allowing it to assume a different identity and NSN, which can then be intensively managed as an US Army asset.

1.2. Message Purpose -

1.2.1. Convert specific Goodrich Internal Hoists to PN 42305-5 configuration.

1.2.2. Instruct the user how to obtain the conversion kit.

2. END ITEMS AFFECTED - All H-60 and UH-1 series aircraft.

3. ASSEMBLIES/COMPONENTS/PARTS AFFECTED - Affected

Assemblies/Components/Parts -

..Nomenclature	PN	NSN
..Hoist, Internal.....	42305-3.....	1730-01-474-1646

.....NOTE.....

UH-1-08-AMAM-01 Hoist

....when complying with the requirements of this message,
....complete forms and records entries IAW DA PAM 738-751.
....ULLS-A units will use appropriate "E" forms.

....
4. INITIAL AIRCRAFT TAMMS (THE ARMY MAINTENANCE MANAGEMENT SYSTEM) ENTRY - Upon receipt of this message, make the following entry on the DA Form 2408-13-1. Enter a Red Horizontal Dash // - // status symbol with the following statement:

- 4.1. H-60 Aircraft: "Comply with requirements of H-60-08-AMAM-05 NLT 5 FEB 08."
- 4.2. UH-1 Aircraft: "Comply with requirements of UH-1-08-AMAM-01 NLT 5 FEB 08."

5. COMPLIANCE REPORTING REQUIREMENTS -

....
.....NOTE.....
....Units will report compliance with this message for
....all assigned aircraft via AMTRACKS. Unit personnel
....designated to submit compliance reports that have not
....registered with AMTRACKS must establish a profile before
....submitting their compliance reports. Access AMTRACKS at
...."<https://amtracks.redstone.army.mil>".

....
5.1. Aircraft Initial Compliance Report - Submit Initial Compliance Report via AMTRACKS NLT 8 FEB 08 IAW AR 750-6. The Initial Compliance Report consists of the Aircraft SN, MDS, Component (Hoist) PN and SN, and date of initial TAMMS entry for all assigned aircraft.

5.2. Aircraft Final Compliance Report - Submit Final Compliance Report via AMTRACKS within 3 days of conversion, but NLT 1 FEB 09 IAW AR 750-6. This report will include the aircraft date of conversion.

5.3. Retail Stock Task/Inspection Compliance Report (Installation level and below) - N/A.

5.4. Wholesale Stock Task/Inspection Compliance Report (Including Depot stock, Depot Maintenance and Single Stock Fund) - N/A.

6. SPECIAL PROVISIONS TO MESSAGE REQUIREMENTS (AIRCRAFT) - Aircraft in Transit (Surface/Air Shipment/Ferry Status/ Aircraft Away From Home Station) - Unit Commanders unable to comply with the requirement specified in para 4 may defer making the initial Aircraft TAMMS entry until arrival at final destination.

....
.....NOTE.....
....Commanders, Facility Managers, and Contractors at all
....levels, including DD 250 aircraft, will not issue aircraft
....until they are in compliance with Para 4 of this message.

7. TECHNICAL PROCEDURES/INSTRUCTIONS -

....
.....NOTE.....
....Applies to All Goodrich Internal Rescue Hoists
....Installed and Not Installed on Aircraft.

....
7.1. Refer to the Hoist Data Plate (located on the left side of the hoist boomhead support assembly) and determine the current PN and SN of the hoist.

7.1.1. If the hoist PN is 42305-1 or 42305R1, no further action is necessary. Proceed to Para 7.3.

7.1.2. If the hoist PN is 42305-3, determine if the SN is in the following list. If on the list, enter a Red Horizontal Dash // - // status symbol on the DA Form 2408-13-1 with the following statement: "Internal Hoist, SN _____ requires conversion to PN 42305-5 NLT 29 JAN 09 IAW H-60-08-AMAM-05/UH-1-08-AMAM-01." Only enter the appropriate aircraft AMAM number in the DA Form 2408-13-1

UH-1-08-AMAM-01 Hoist

statement.

..20029...20112...20128...20134...20142...20147...20149...20154
..20156...20159...20161...20162...20170...20173...20175...20184
..20190...20216...20218...20224...20225...20227...20241...20248
..20255...20256...20260...20265...20277...20280...20283...20286
..20288...20292...20299...20306...20310...20312...20319...20325
..20326...20333...20336...20338...20364...20365...20376...20383
..20391...20401...20403...20415...20419...20421...20480...20483
..20485...20492...20493...20496...20499...20506...20507...20508
..20519...20529...20531...20540...20550...20560...20562...20583
..20586...20588...20589...20600...20601...20652...20681...20686
..20721

7.1.3. If the hoist PN is 42305-3, but not included in the serial numbers listed above, notify the POC listed in Para 13.2.1. for additional information.

7.1.4. There are 15 additional hoists to be delivered in the 42305-3 configuration. New hoists received after the message DTG are subject to the requirements of this message. Contact the POC listed in Para 13.2.1 if the hoist SN is not listed.

7.2. Contact the POC listed in Para 13.2.1 NLT 5 FEB 08 to coordinate obtaining a conversion kit. Units will provide hoist PN, SN, and a Unit POC with all contact information. Complete procedures for conversion of PN 42305-3 hoists are contained within the Kit.

7.3. Clear the initial entry from 4 and note compliance on DA Form 2408-15.

8. PROCEDURES/INSTRUCTIONS FOR ASSEMBLIES/COMPONENTS/PARTS IN WORK OR IN STOCK (AT ALL LEVELS INCLUDING WAR RESERVES) - N/A.

9. SPECIAL TOOLS AND FIXTURES REQUIRED - N/A.

10. SUPPLY/PARTS (REQUISITION/DISPOSITION) -

10.1. Parts Required -

..Nomenclature	PN/NSN	Qty
..Conversion Kit	42305-48	lea
.....	1680-01-552-3840	

10.2. Bulk and Consumable Materials - N/A.

10.3. Requisitioning Instructions - Contact PM POC in 13.2.1 for assistance in obtaining kits.

10.4. Disposition of Discrepant Parts/Components - The POC listed in 13.2.1 shall provide instructions to return the 42305-3 Serial Numbered Data plate for accountability.

10.5. Disposition of Hazardous Material - N/A.

11. MAINTENANCE APPLICATION -

11.1. Category of maintenance - AVUM.

11.2. Estimated Time Required -

11.2.1. Time to complete inspection - Total of 0.2 man-hours using 1 person.

11.2.2. Time for conversion - Total of 1.0 man-hour using 1 person.

12. PUBLICATION REQUIREMENTS -

12.1. References -

12.1.1. AR 750-6.

12.1.2. DA Pam 738-751.

12.1.3. AWR 1308R3 (UH-60), Appendix D-3.

12.1.4. AWR TTS 34894 (UH-1), Appendix D-3.

12.2. Publication Changes - N/A.

13. POINTS OF CONTACT -

13.1. Technical POCs are -

13.1.1. H-60 Primary - Mr. Pete Fengl (Camber Corporation), AMSRD-AMR-AE-U, DSN 897-3121 or (256) 313-3121. Fax is 897-3199 or (256) 313-3199. Email is "pete.fengl@us.army.mil".

13.1.2. H-60 Alternate - Mr. Mark Coble, AMSRD-AMR-AE-U, DSN 897-3104 or (256) 313-3104. Fax is 897-3199 or (256) 313-3199. Email is "mark.a.coble@us.army.mil".

UH-1-08-AMAM-01 Hoist

- 13.1.3. UH-1 Primary - Mr. Darrell Hutson , AMSRD-AMR-AE-BG, DSN 897-2231 or commercial (256) 313-2231. Fax is (256) 313-3206. Email is "Darrell.Hutson@us.army.mil".
- 13.1.4. UH-1 Alternate - Mr. Roger Redick (westStar), AMSRD-AMR-AE-BG, DSN 897-2431 or (256) 313-2431. Email is "Roger.Lowe.Redick@us.army.mil".
- 13.2. Project/Product Manager's (PM) Office POCs are -
 - 13.2.1. Item Manager - Mr. Ricky Terrell, SFAE-AV-UH-L, DSN 897-0765 or (256)313-0765 Email is "Rick.terrell@us.army.mil".
 - 13.2.2. H-60 POC - Mr. Charles Strowbridge, SFAE-AV-UH-L, DSN 645-7898 or (256)955-7898. Fax is DSN 897-5572 or (256)313-5572. Email is "charles.strowbridge@us.army.mil".
 - 13.2.3. UH-1 POC - Mr. Howard Lee Reeves, SFAE-AV-AS-ASH-L, DSN 645-9701 or (256) 955-9701. Fax is 645-7125 or (256) 955-7125. Email is "howard.reeves@peoavn.redstone.army.mil".
- 13.3. Forms and Records POCs are -
 - 13.3.1. Primary - Ms. Ann Waldeck, AMSAM-MMC-MA-NM, DSN 746-5564 or (256) 876-5564. Fax is DSN 746-4904 or (256) 876-4904. Email is "ann.waldeck@conus.army.mil".
 - 13.3.2. Alternate - Ms. Sibyl Johnson, AMSAM-MMC-MA-NM, DSN 788-6696 or (256) 842-6696. Fax is DSN 746-4904 or (256) 876-4904. Email is "sibyl.johnson@conus.army.mil".
- 13.4. Safety POCs are -
 - 13.4.1. Primary - Mr. Steve Lindsey (SAIC), AMSAM-SF-A, DSN 897-2092 or (256) 313-2092. Fax is DSN 897-2111 or (256) 313-2111. Email is "steven.lindsey@us.army.mil".
 - 13.4.2. Alternate - Mr. Ron Price, AMSAM-SF-A, DSN 788-8636 or (256) 842-8636. Fax is DSN 897-2111 or (256) 313-2111. Email is "ron.pricel@conus.army.mil".
- 13.5. Foreign Military Sales POC is Mr. Ronnie W. Sammons, AMSAM-SA-AS-UT, DSN 897-6825 or (256) 313-6825. Fax is DSN 897-0411 or (256) 313-0411. Email is "ronnie.sammons@conus.army.mil".
- 13.6. After hours, contact the AMCOM Operations Center (AOC) DSN 897-2066/7 or (256) 313-2066/7.