

UH-1...

Escutcheon Plate Fix

If vibration is taking its toll on the escutcheon plates under the door handles of your Huey, stop the wear and tear with inserts, NSN 1680-01-113-0167.

The nylon inserts fit inside the escutcheon and keep the handles from rubbing on the thin aluminum edge of the escutcheon. This provides an extra bearing surface and gives the plate longer life.