

PRIORITY

PTTUZEXN RULNNAC2797 8778236-UUUU--RUKMDTA;
ZNR UUUUU
FM CDR ARNG EDGEWOOD MD //NGB-AVN-L//
TO AIG 7481
INFO RUEFHQA/CNGB WASHDC //CNGB-ARL-A//
P R ~~171945Z MAR 77~~ ZFF4 180236Z MAR 77
FM CDRAVSCOM STL MO //DRSAV-FEU//
TO AIG 8881
AIG 9884
INFO CDRUSABPA FT WORTH TX //SAVSE-6//
CDRUSASAFSCOM HUNTSVILLE AL
CDRUSA AVNO FT RUCKER AL

ARMY

UH-1-77-9
Clarification to
77-8

BT
UNCLAS
AIG 9884 TAKE FOR INFO
NOTE - THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT
HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES;
ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL
SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED,
INCLUDING BOTH MAINTENANCE AND SUPPLY ELEMENTS; THE RETRANSMITTAL

PAGE 2 RULNNAC2797 UNCLAS
SUBJ - AMENDMENT TO MSG 152288Z MAR 77 PERTAINING TO CLARIFICATION
OF TAIL ROTOR ASSEMBLY PUBLICATION CHANGE ON UH-1/AH-1 HELICOPTERS;
{UH-1-77-9} AND {AH-1-77-7};

NOTE - SUBJECT MESSAGE IS AMENDED TO INCLUDE AVSCOM CONTROL
NUMBERS UH-1-77-9 AND AH-1-77-7 THAT WERE OMITTED:

1. THE PURPOSE OF THIS MESSAGE IS TO CLARIFY MESSAGE UH-1-77-8
AND AH-1-77-6, THE MESSAGE'S PRIMARY INTENT WAS TO EXTEND THE 12
HOUR INSPECTION TO 25 HOURS ON ALL UH-1 AND AH-1 WITH SILENT CHAINS.
THE SAME INSPECTION THAT WAS PERFORMED AT 12 HOURS WILL NOW BE
PERFORMED AT 25 HOURS, THE INSPECTION OF THE CHAIN DESCRIBED IN
PARA 20 OF MESSAGE UH-1-77-8 AND AH-1-77-6 IS TO BE PERFORMED AT
EACH 125 HOURS AND NOT TO BE PERFORMED AT THE 25 HOUR INTERVAL.

NOTE - SILENT CHAIN INSPECTION SHOULD REMAIN ON DA FORM 2428-18; BUT
THE INTERVAL SHOULD BE CHANGED FROM 12 HOURS TO 25 HOURS;

2. IF ADDITIONAL INFORMATION OR CLARIFICATION IS REQUIRED, PLEASE
CONTACT MR. JIM BOEN, AUTOVON 698-5666 OR COMMERCIAL 314-268-5866;

BT
88797

18 MAR 77 03 12

PRIORITY

PAAUZEKX RULNNAC0767 0750227-UUUU--RUMMDTA.

ZNR UUUUU

P R 160227Z MAR 77 ZEX

FM CDR ARNG-OAC EDGEWOOD MD //NGB-AVN-L//

TO AIG 7421

INFO RUEFHQA/CNGB WASH DC //NGB-ARL-A//

P R 152200Z MAR 77

FM CDR USAAVSCOM STL MO //DRSAV-FEU//

TO AIG 8881

BT

UNCLAS

NOTE CLN THIS IS A MAINTENANCE ADVISORY MESSAGE AND HAS NOT, REPEAT HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED, INCLUDING BOTH MAINTENANCE AND SUPPLY ELEMENTS. THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.

SUBJ CLN CLARIFICATION OF TAIL ROTOR ASSEMBLY PUBLICATION CHANGE ON UH-1/AH-1 HELICOPTERS (UH-1-77-9) AND (AH-1-77-7).

1. THE PURPOSE OF THIS MESSAGE IS TO CLARIFY MESSAGE UH-1-77-6 AND AH-1-77-6. THE MESSAGE'S PRIMARY INTENT WAS TO EXTEND THE 10 HOUR INSPECTION TO 25 HOURS ON ALL UH-1 AND AH-1 WITH SILENT CHAINS,

ARMY

PAGE 2 RULNNAC0767 UNCLAS

THE SAME INSPECTION THAT WAS PERFORMED AT 10 HOURS WILL NOW BE PERFORMED AT 25 HOURS. THE INSPECTION OF THE CHAIN DESCRIBED IN PARA 20 OF MESSAGE UH-1-77-6 AND AH-1-77-6 IS TO BE PERFORMED AT EACH 100 HOURS AND NOT TO BE PERFORMED AT THE 25 HOUR INTERVAL. NOTE CLN SILENT CHAIN INSPECTION SHOULD REMAIN ON DA FORM 2400-18, BUT THE INTERVAL SHOULD BE CHANGED FROM 10 HOURS TO 25 HOURS.

2. IF ADDITIONAL INFORMATION OR CLARIFICATION IS REQUIRED, PLEASE CONTACT MR. JIM BOEN, AUTOVON 690-5266 OR COMMERCIAL 314-268-5066.

BT

#0767

16

16 MAR 77 03 00Z

MNNN