

# THE RIGHT PUMP

Dear Editor,

Mechanics, and even TI's at units I've served with, don't agree on whether *Seq. No. 5.31, TM 55-1520-210-PMS* refers to an oil pump or to fuel pumps.

The Huey -20 and -34 make no reference to a "power driven rotary (booster) pump," but that's what the PMS says to inspect.

So, some mechanics inspect the fuel pumps. This is wrong! The right pump is described in paras 1-58 thru 1-63, and shown as item 3, fig 5-41 of *TM 55-2840-229-24*, on T 53 engines.

Please pass on the word.

SP6 James G. Neal  
Ft. Meade, MD

(Ed Note—Thanks for the careful eye!)

