

message 121730Z
Sept 1975
ign + door locks

13/0125Z

Gen 75-2
door locks

ARMY

TTTUZEKA RUCBADA646 2551976-0000--NUNKDTA;
ZNR UNCLAS 121730Z SEP 75 25X
FM ARNG-OAG SDBR000 HQ //JAC-AVM-L//
TO AIG 7401
INFO ADFPRA/C/55 WASH DC //JGO-ARL-A//
BT
UNCLAS

SURJ CLM STATUS REPORTING OF ACFT DOOR LOCK DEVICE AND IGNITION SWITCH LOCK INSTL (RCS AND 232)

- A, DA MSG, DALG-JA, 251127Z JUN 74, SUBJ CLM ACFT SYS SECURITY DEVICES,
- B, MWO 55-1580-224-32-1 (DOOR LOCK DEVICES) AH-1, UH-1, OH-47, OH-54, OH-5, OH-54, OV-1;
- D, MWO 55-1522-221-32-51 (IGNITION SWITCH LOCK) AH-1;
- E, MWO 55-1578-219-32-5 (IGNITION SWITCH LOCK) UH-1;
- F, MWO 55-1588-218-32-58 (IGNITION SWITCH LOCK) OH-47;
- G, MWO 55-1528-217-32-54 (IGNITION SWITCH LOCK) OH-54;
- H, MWO 55-1522-214-32-44 (IGNITION SWITCH LOCK) OH-6;
- I, MWO 55-1528-228-32-27 (IGNITION SWITCH LOCK) OH-55;
- J, MWO 55-1518-204-32-49 (IGNITION SWITCH LOCK) OV-1;

PAGE 2 RUCBADA646 UNCLAS

K, MSG, OAG-AVM-L, ARNG-OAG, 192142Z DEC 74,
MSG IN TWO PARTS

PART 1 FOR ALL

1. THE PURPOSE OF MSG IS TO PROVIDE ADDED EMPHASIS ON THE PROMPT APPLICATION OF THESE URGENT MWO'S AND TO MODIFY THE PRESENT REPORTING SYS.

2. REF A REQUESTED THAT DA BE SENT A MONTHLY STATUS REPORT ON INSTL OF ACFT SECURITY DEVICES (AK THE REF MWO'S). DA IS CONCERNED THAT THE INSTL OF DOOR LOCK DEVICES AND IGNITION SWITCH LOCKS FOR SECURITY ARMY ACFT BE COMPLETED EXPEDITIOUSLY AND REPORTED

IMMEDIATELY. IN ORDER TO PROVIDE DA W A TIMELY RECORD OF SECURITY DEVICE INSTL, REF B ESTABLISHES A MONTHLY RCS REPORT, SURJ AS ABOVE.

IT IS ANTICIPATED THAT APPROPRIATE COMMAND SUPERVISION WILL INSURE TOTAL COMPLIANCE AT THE NEXT 30 TO 60 DAYS.

3. THE REPORT WILL CONSIST OF THE STATE REPORTING AND THE FOL
FORMAT:

- A, ACFT SYS REPORTED
- B, DENSITY OF SYS REPORTED
- C, NO OF ACFT BY SYS ON WHICH IGNITION SWITCH LOCKS HAVE BEEN INSTALLED;

PAGE 3 RUCBADA646 UNCLAS

D, NO OF ACFT BY SYS ON WHICH DOOR LOCK DEVICES HAVE BEEN

11-7

16 Jan 76 21 46z

acft locking device + ign lock switch

GA-75-2

ARMY/13

RATUZEXN RULNEAA8395 2161989-UUUU-2RUMKDTA;
UNCLAS UUUUU
161982Z JAN 76 ZEX
FM ARNG-OAC BDOEMOOD MD //OAC-AVN-L//
TO AIG 7481
INFO RUEFHQA/CNGB WASH DC //NGB-ARC-A//
RUHTTFA/CDR USAAVSCOM STL MO //AHSV-FHR//
BT

UNCLAS
SUBJ OLN ACFT LOCKING DEVICES AND IGNITION SWITCH LOCK INSTALLATION
CDR USAAVSCOM MSG 092032Z JAN 76 (NOTAL);
MWO 55-1528-224-38-1, 28 DEC 74, SUBJ OLN INSTL OF DOOR LOCK
DEVICES (AH-1, UH-1, OH-47, OH-54, OH-6, OH-58, AND OV-10 SERIES
ACFT);
MWO 55-1528-218-38-58, 19 NOV 74, SUBJ OLN INSTL OF ACFT
ELECTRICAL IGNITION SYSTEM SECURITY DEVICES (OH-47A/B/C);
MWO 55-1518-224-38-146, 18 NOV 74, SUBJ OLN INSTL OF ACFT
ELECTRICAL SOCY DEVICES (OV-10, OV-10, OV-10 AND OV-10 ACFT);
MWO 55-1528-214-38-144, 18 NOV 74, SUBJ OLN INSTL OF ACFT
ELECTRICAL IGNITION SOCY DEVICE (OH-54 HEL);
MWO 55-1528-217-38-64, 19 NOV 74, SUBJ OLN INSTL OF ACFT
ELECTRICAL IGNITION SOCY DEVICE (OH-54A/B);

PAGE 2 RULNEAA8395 UNCLAS
MWO 55-1528-221-38-51, 22 NOV 74, SUBJ OLN INSTL OF ACFT
ELECTRICAL SOCY DEVICE (AH-10, AH-10 AND TH-10 HEL);
MWO 55-1528-225-38-127, 14 FEB 75, SUBJ OLN INSTL OF ACFT
ELECTRICAL IGNITION SOCY DEVICE (OH-58A HEL);
MWO 55-1508-219-38-5, 21 NOV 74, SUBJ OLN INSTL OF ACFT
ELECTRICAL IGNITION SOCY DEVICE (UH-1B/C/D/H/M HEL);
ACFT RECEIVED FROM THE DEPOT OVERHAUL PROGRAM SINCE 1 NOV 75
SHOULD HAVE APPLICABLE ACFT LOCKING AND IGNITION ELECTRICAL SOCY
DEVICES APPLIED;
REQUEST YOU FURNISH A LISTING OF ACFT RECEIVED SINCE 1 NOV 75
WITHOUT APPLICATION OF THE REFERENCED MWO TO CDR USAAVSCOM,
ST LOUIS, MO, ATTN OLN AHSV-FHR, WITH INFO CY TO ARNG OPERATING
ACTIVITY CENTER, ATTN OLN OAC-AVN-L, IN THE FOLLOWING FORMAT OLN
STATE AND FACILITY REPORTING;
ACFT MODEL, DESIGN, AND SERIES;
MWO(S) NOT COMPLIED WITH;
DEPOT AND DATE OF RECEIPT;
REPORT SHOULD BE RECEIVED NLT 30 JAN 76; NEGATIVE REPORTS
ARE NOT REQUIRED;

All Acft have been mod from overhaul

(41)

18 DEC 75 22 03z

*excess cmm rotary
lock switch*

RTTUZEXH RULNEAA1040 3522020#UUUU#-RUKMDTA;
ZNR UUUUU
~~BT 101918Z DEC 75 ZEX~~
FM ARNG OAC EDGEWOOD MD //OAC-AVN-L//
TO AIG 7401
INFO RUBPHQA/CNGB WASH DC //NGB-ARL-A//
RUWTFFA/ODR USAAVSCOM STL MO //ANSAY-QKSG//

ARMY

BT
UNCLAS
PASS TO EA USPFO ABOVE
SUBJECT CLN EXCESS SWITCH CMM ROTARY LOCKS CMM NSN 2995-02-552-8747
1. REQUEST THAT SACS CONSOLIDATE QUANTITIES OF SUBJ LOCKING DEVICE
WHICH ARE EXCESS OR SHORT TO MWQ COMPLIANCE REQUIREMENTS AND RENDER
A REPORT TO ARNG HALO CMM ATTN CLN CWS NOWICKI CMM AUTOVON 584-2029 CMM
NLT COB 9 JAN 76
2. NEGATIVE REPORTS ARE REQUIRED;

BT
1040
lx

NNNN

*C/W
22 Dec 75
Larry
Lacey*