

We got gigged for not having heat shield FSN 1560-757-4867 on our UH-1B to protest the No. 1 hanger bearing.

Is it really necessary?

