

LV # 16003 TIME 0720 ADDR 130/84

IMMEDIATE

Z:BNM 2437M 452FTS 264F RERO ACD ACF ADC ACE-DET ABG/CC FTM/CC AUDITOR  
CAP 207419S COMSEC DAPD W/D0 D0J D10C D00S D00Z D0TM DPC DPM FCS IAOM  
N LCC L03 L0T NA NAVY WMAX 001 0T PA SE SG SS SSF SV T/A WEA XPMT XPR

UNCLAS RUCIFR08773 1300710-0000--RUMNDA.

00000  
190710Z MAY 84 ZEN  
R RUC ARMG SAC APS MD//NSD-AVM-LD//  
R RTG 7461  
OCT PA-BHCSVD  
190200Z MAY 84  
R CDRAVSCOM STL NO//ANSAY-HE//  
R RTG 8831  
LG 0004  
LG 070A  
LG 0515  
LG 0042

*on*  
*TIB*  
*725*  
*ARMY*  
*NO HOLD*  
*TILL*  
*A.M.*

DEMPA/US EMBASSY ROME ITALY//ODC/PASS TO HQ NFO//  
REMBRE/US EMB PROT AGY REGION II 20 FEDERAL PLAZA NY NY  
DCLFOR/NOAA OF CO ACFT OPERATIONS ACFT MAINT DIV MIAMI FL  
3102 (RELEX NO 008199)  
DCHIN/AIT TAIPEI TAIWAN  
DENC/AIT WASH DC  
DENTH/COMUSMILCP SAN SALVADOR EL SALVADOR//SCIS-AF//  
DNETC/COMUSMILCP YEGUCIGALPHA NO  
DENBO/COMUSMILCP BOGOTA COLUMBIA//SCCD-RFDCH//  
DENDIR/COMJTF-6 PALMEROLA AB NO//AVM//  
DENDDA/CDAMICOM REDSTONE ARSENAL AL//ANSNI-ST//  
RUCIFR08773 UNCLAS  
DENHAD/US CUSTOMS SERVICE DEPT OF TREASURY WASH DC  
NET RUCENTY/CUSDAA TEL AVIV ISRAEL//RFO//  
DENC/SEC STATE WASH DC//REA/RFO//  
DENHAA/HQS MAC SCOTT AFB IL//LGMAB/DDW/IGF//  
DENADA/USDOCC LANDSOUTHEAST IZMIR TU//AV//  
DENPWA/DISC PHILADELPHIA PA//DEBB-JU//  
DENST/CRUSMAG BANGKOK THAILAND  
DVAAT/NSDCLOSING MELBOURNE AU//SOAIRENG//

AVNPT/DEFRAE TECHN CANBERRA AU//DAIRENG-AF//  
DEAFPE/AUSTAIR WASH DC//BENGSO//  
DENLFL/USDA FOREST SERVICE PO BOX 2417 WASH DC  
/COOPERATIVE FIRE PROTECTION//  
DPCPLA/LOG COM OTTAWA CANADA//DTHRM-2//  
OCT PA-BHCSVD

UNCLAS SECTION 1 OF 2  
LG 0004 TAKE FOR INFO ONLY  
LG 0700 TAKE FOR INFO ONLY  
LG 0515 TAKE FOR INFO ONLY  
AGE 4 RUCIFR08773 UNCLAS  
LG 0042 TAKE FOR INFO ONLY

SUBJECT - SAFETY-OF-FLIGHT MESSAGE, TECHNICAL, UH-1/EH-1 SERIES AIR-  
RAFT, REVISIONS TO INSPECTION OF TRUHHION BEARINGS (UH-1-84-07)  
TRUHHION BEARINGS (UH-1-84-07)

REPORTING SUSPENSE DATE - NO CHANGE.  
TRUHHION INSPECTION SUSPENSE DATE - NO CHANGE.  
NOTE - THIS IS A SAFETY-OF-FLIGHT MESSAGE AND HAS NOT, REPEAT, HAS  
NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.

*UH-1-86-07*  
*TruHHion bearings*

ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE. ALL SUB-  
ORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTED OF CONCERNED. THE  
RETRANSMITTAL SHALL REFERENCE THIS MESSAGE. ACTION ADDRESSEES WILL  
IMMEDIATELY VERIFY THIS RETRANSMISSION TO COMMANDER, AVSCOM, ATTN-  
NSAN-HE (SOF COMPLIANCE OFFICER).

REFERENCE -

(1) AVSCOM MESSAGE 111815Z MAY 86, SUBJ: SAFETY OF FLIGHT  
MESSAGE, TECHNICAL, RCS CSSLD 1860 (R1), UH-1/HH-1 SERIES AIRCRAFT,  
RE TIME INSPECTION OF TRUNNION BEARINGS (UH-1-86-06)  
TR 55-1520-242-20-21).

(2) TR 55-1520-210-23-1, AVIATION UNIT AND INTERMEDIATE INSTRU-  
MENT 5 RUCIFRDA773 UNCLAS  
INSPECTION ARMY MODEL UH-1, H/HH-1H HELICOPTERS DATED 20 FEB 79 AND  
CHANGES THROUGH CHANGE 53, 29 JAN 86.

SUMMARY OF PROBLEM.

A. FEEDBACK FROM THE FIELD INDICATES THAT INSPECTION CRITERIA  
OF REFERENCE (1) MESSAGE WERE MORE STRINGENT THAN NECESSARY. THE  
INSPECTION CRITERIA HAVE BEEN REVIEWED. THIS MESSAGE REVISES THE  
INSPECTION CRITERIA.

B. THE PURPOSE OF THIS MESSAGE IS TO PROVIDE THE NEW INSPECTION  
CRITERIA. COMPONENTS/AIRCRAFT WHICH HAVE PREVIOUSLY PASSED THE ORI-  
GINAL INSPECTIONS NEED NOT BE REINSPECTED. THOSE REJECTED UNDER  
THE ORIGINAL CRITERIA SHOULD BE RE-EVALUATED TO DETERMINE IF THEY  
CAN PASS.

PRIORITY CLASSIFICATION - SUBPARAGRAPH 2F IS REVISED TO:

F. COMPONENTS IN STOCK AT ALL LEVELS - UNITS WILL INSPECT COMPO-  
NENTS LISTED IN PARAGRAPH 4 BELOW PRIOR TO INSTALLATION.

END ITEMS TO BE INSPECTED - NO CHANGE

ASSEMBLY COMPONENTS TO BE INSPECTED - NO CHANGE

LNKED

10074 0727 139/86

72080V 340TH 437FTS 2CAF PERG ACD ACP ADC ACE-DET ABG/CC PTM/CC AUDITOR  
CAP 203410Z COMSEC OAPD W/DO DOJ 300C 060S 060Z 060M 06C DPM FCS IR0W  
W LSC LGS LGY MA NAVY NEAX 011 01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00

BTUZXU PULNEAR2774 1390710-UNCLAS--RUWHDIA.  
BT UUUUU  
190710Z MAY 86 ZEX  
RGP APNG OAC APO HD//MGB-AVN-LD//

SSI  
ARMY

TO AIG 7401  
OCCF-~~DA-SHCSUD~~  
L 190700Z MAY 86  
FM COMAVSCOM STL HQ //ASAV-WE//  
TO AIG 8841  
AIG 9004  
AIG 870A  
AIG 7513  
AIG 9042  
RUCMRO/US EMBASSY ROME ITALY //ODC/PASS TO HQ MFO//  
RUCVBAE/US EMB PROT AGY REGION 11 20 FEDERAL PLAZA NY NY  
RUCLEFOR/HOAP OF LO ACFT OPERATIONS ACFT MAINT DIV MIAMI FL  
33102 (RELEX NO 208199)  
RUEHIN/AIT TAIPEI TAIWAN  
RUEHNC/AIT WASH DC  
RUEHNS/COMUSMILGP SAN SALVADOR EL SALVADOR //SCIS-AF//  
RUEHNS/COMUSMILGP TECUCIGALPA HO  
RUEHNS/COMUSMILGP BOGOTA COLUMBIA //SCIS-AF//  
RUEHNS/COMJTF-5 PALMEROLA AB HO //AVN//  
RUCGDA/COMMICON REDSTONE ARSENAL AL //AMSMI-ST//  
RUCVHAD/US CUSTOMS SERVICE DEPT OF TREASURY WASH DC

PAGE 2 RUCIFR08774 UNCLAS  
RUEHNY/CUSDAO TEL AVIV ISRAEL //MFO//  
RUEHNC/SEC STATE WASH DC //MFA/MFO//  
RUCURAA/HQS MAC SCOTT AFB IL //LGMV/D0V/IG//  
RUEHNER/USDOCS LANDSOUTHERST IZMIP TU//AV//  
RUCORMA/DISC PHILADELPHIA PA //SEED-JU//  
RUEHNT/COMUSMAG BANGKOK THAILAND  
RUCVAAI/HDSCLOENG MELBOURNE AU //SOAIRENG//  
RUCVAPP/DEFATF TECHN CANBERRA AU //DAIRENG-AF//  
RUCVAKYE/POSTAIR WASH DC //SENGS//  
RUEHNF/USDA FOREST SERVICE PO BOX 2417 WASH DC //COOPERATIVE FIRE  
PROTECTION//  
RUCPCLA/LOG CON OTTAWA CANADA //DTHEML-2//  
OCCF DA-SHCSUD

BT  
UNCLAS FINAL SECTION OF 2  
AIG 9004 TAKE FOR INFO ONLY  
AIG 870A TAKE FOR INFO ONLY  
AIG 7513 TAKE FOR INFO ONLY  
AIG 9042 TAKE FOR INFO ONLY  
PARTS TO BE INSPECTED - NO CHANGE.

PAGE 3 RUCIFR08774 UNCLAS  
6. APPLICATION - SUB PARAGRAPH 10 IS REVISED TO

- D. PUBLICATIONS WHICH REQUIRE CHANGE -
- (1) REFERENCE C(2) WILL BE REVISED TO REQUIRE PULL TEST ON OUTER RING TRUNNIONS ONLY.
  - (2) REFERENCE C(2) WILL BE REVISED TO REQUIRE INSPECTION PRIOR TO INSTALLATION.
  - (3) REFERENCE C(2) WILL BE REVISED TO ALLOW SCRATCHES UP TO .005 INCH DEPTH IN BORES
1. SUPPLY/PARTS AND DISPOSITION - NO CHANGE.
2. SPECIAL TOOLS/JIGS AND FIXTURES - NO CHANGE.
3. INSPECTION PROCEDURES - DELETE EXISTING PARAGRAPH AND REPLACE WITH (SEE REF C(2), CHAPTER 5).
- A. INSPECT ALL FIVE TRUNNION BEARINGS (FIGURE 5-34, ITEM 10) PER PARAGRAPH 5-40B FOR WEAR, UNIDBALL CRACKS AND PROPER INSTALLATION. TRUNNION BEARING P/N KSP9001-3/3 SHALL BE CHECKED FOR CRACKS ON BOTH SIDES OF THE UNIDBALL USING MAGNIFICATION FROM 5 TO 10 POWER.
- B. CHECK TWO TRUNNION IN THE OUTER RING FOR PROPER INSTALLATION. DISASSEMBLE AS FOLLOWS AND CONTINUE INSPECTION -
- (1) DISCONNECT DRIVE LINKS FROM SWASHPLATE OUTER RING (2 LACES) PER PARAGRAPH 5-78C.

PAGE 4 RUCIF08774 UNCLAS

- (2) REMOVE TRUNNION BEARINGS PER PARAGRAPHS 5-42 F AND H. HANDLING DURING REMOVAL OF NUTS AND BOLTS OR DAMAGE ON THE SHANK OF THE BOLTS MAY INDICATE IMPROPER INSTALLATION.
  - C. CHECK EACH TRUNNION SHAFT FOR FRETTING WEAR OR OTHER DEFECTS.
  - D. CHECK OUTER RING BORES FOR SCRATCHES. SCRATCHES UP TO .005 INCH DEPTH AND WIDTH ARE ACCEPTABLE IN BOTH INNER AND OUTER RING BORES.
  - E. INSTALL SERVICEABLE TRUNNIONS IN SWASHPLATE PER REF C PARAGRAPHS 5-42 F AND T. DO NOT INSTALL BOLTS. REF C(2), FIGURE 5-37, ITEMS 7, 8, AND 27. PERFORM PULL TEST PER WARNING NOTE ON PAGE 5-84, PARAGRAPH 47. COMPLETE INSTALLATION OF TRUNNIONS PER PARAGRAPH 5-44.
- NOTE - BOLTS MUST BE PUSHED THROUGH BY HAND AND BE PERFECTLY ALIGNED WITH THE GROOVES ON TRUNNION SHAFT TO AVOID SAFETY OF FLIGHT CONDITIONS.
- F. CONNECT DRIVE LINKS TO SWASHPLATE OUTER RING PER PARAGRAPH 5-44C OF REFERENCE C(2).
  - G. CORRECTION PROCEDURES - NO CHANGE
  - H. WEIGHT AND BALANCE - NO CHANGE.
  - I. RECORDING AND REPORTING REQUIREMENTS - NO CHANGE

PAGE 5 RUCIF08774 UNCLAS

1. POINTS OF CONTACT.
  - A. FOREIGN MILITARY SALES (FMS) RECIPIENTS REQUIRING NOTIFICATION OF ACTION ADVISED BY THIS MESSAGE SHOULD CONTACT CW4 JOHN SANDOM, AUTOVON 693-2106 OR COMMERCIAL (314) 263-2106.
  - B. TECHNICAL POINT OF CONTACT FOR THIS MESSAGE IS MR. KEN DEER, AUTOVON 693-1675 OR COMMERCIAL (314) 263-1675.
  - C. LOGISTICAL POINT OF CONTACT FOR THIS MESSAGE IS MR. DEAN ASTROM, AUTOVON 693-1228 OR COMMERCIAL (314) 263-1228.
  - D. FORMS AND RECORDS POINT OF CONTACT FOR THIS MESSAGE IS MR. M. DENNIS, AUTOVON 693-1955 OR COMMERCIAL (314) 263-1955.
  - E. MESSAGE POINT OF CONTACT IS MR. LYELL MYERS, AUTOVON 693-2300 OR COMMERCIAL (314) 263-2300.

Rcvr @11M/2.02194 Line: 28

REC'D

JUN 05

4755210EVDL

0442139 A 1-11-01-006056 FTS SVC 6513232  
OATUZYUW RUCIFRD8773 1390139-UJAC--RUEVDFL  
INR UUUAC

O 190200Z MAY 86

FM CDRAVSCOM STL MO//AMBAV-ME//

TO AIG 8881

AIG 9004

AIG 8708

AIG 7515

AIG 9042

RUEHRD/US EMBASSY ROME ITALY//ODC/PASS TO HQ MFO//

RUEVDAE/US EVN PROT ASY REGION 11 20 FEDERAL PLAZA NY NY

RUCLFOR/NOAA OF CO ACFT OPERATIONS ACFT MAINT DIV MIAMI FL

33102 (RELEX NO 008199)

RUEHIN/AIT TAIPEI TAIWAN

RUEHC/AIT WASH DC

RUEHSN/COMUSMILGP SAN SALVADOR EL SALVADOR//SCIS-AF//

RUEHTG/COMUSMILGP TEGUCIGALPHA HO

RUEHBO/COMUSMILGP BOSOTA COLUMBIA//SCCD-AFDCH//

RUCIDNA/COMJTF-B PALMEROLA AB HQ//AVN//

RUCDSDA/CDRMIACOM REDSTONE ARSENAL AL//AMSKI-ST//

PAGE 3 RUCIFRD8773 UNCLAS

RUEVHAD/US CUSTOMS SERVICE DEPT OF TREASURY WASH DC

INFO RUEHTY/CUSDAO TEL AVIV ISRAEL//MFO//

RUEHC/SEC STATE WASH DC//NEA/MFO//

RHCURAA/HQS MAC SCOTT AFB IL//LGMWB/DOV/IG//

RJFLAEA/USDOC LANDSOUTHEAST IZMIR TU//AV//

RUEOPNA/DISC PHILADELPHIA PA//QEBB-JU//

RUEHBT/COMUSMAG BANGKOK THAILAND

RAYAAC/HQSCLOGENG MELBOURNE AS//SDAIRENS//

RAYWPP/DEFAIR TECHN CANBERRA AS//DAIRENS-AF//

RUEAKKE/AUSTAIR WASH DC//SENGSO//

RUEVDFL/USDA FOREST SERVICE PO BOX 2417 WASH DC

//COOPERATIVE FIRE PROTECTION//

RCCPCLA/LOS COM OTTAWA CANADA//DTHEM6-2//

ACCT DA-BHCSVD

BT

UNCLAS SECTION 1 OF 2

AIG 9004 TAKE FOR INFO ONLY

AIG 8708 TAKE FOR INFO ONLY

AIG 7515 TAKE FOR INFO ONLY

PAGE 4 RUCIFRD8773 UNCLAS

AIG 9042 TAKE FOR INFO ONLY

SUBJECT - SAFETY-OF-FLIGHT MESSAGE. TECHNICAL. UH-1/EH-1 SERIES AIR-

RAFT. REVISIONS TO INSPECTION OF TRUNNION BEARINGS (UH-1-86-07)

(55-1520-242-20-21).

A. REPORTING SUSPENSE DATE - NO CHANGE.

B. TASK/INSPECTION SUSPENSE DATE - NO CHANGE.

NOTE - THIS IS A SAFETY-OF-FLIGHT MESSAGE AND HAS NOT. REPEAT. HAS

NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES.

ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUB-

ORDINATE UNITS. ACTIVITIES OR ELEMENTS AFFECTED OF CONCERNED. THE

*FS*  
*UH-1-86-07*  
*trunnion bearings*  
*swashplate*

STATE & PRIVATE  
FORESTRY STAFF

JUN 05 1986

*AW @ next 100*  
*hr. dup.*  
*cgill 8/2/86*

RECEIVED - WFO

MAY 26 1986

RETRANSMITTAL SHALL REFERENCE THIS MESSAGE. ACTION ADDRESSEES WILL IMMEDIATELY VERIFY THIS RETRANSMISSION TO COMMANDER, AVSCOM, ATTN: AMSAV-ME (SOF COMPLIANCE OFFICER).

C. REFERENCE -

(1) AVSCOM MESSAGE 111815Z MAY 86, SUBJ: SAFETY OF FLIGHT MESSAGE, TECHNICAL, RCS CSGLD 1860 (R1), UH-1/EH-1 SERIES AIRCRAFT, ONE TIME INSPECTION OF TRUNNION BEARINGS (UH-1-86-06) (TB 55-1520-242-20-21).

(2) TM 55-1520-210-23-1, AVIATION UNIT AND INTERMEDIATE INSTRUMENTS ARMY MODEL UH-1H/EH-1H HELICOPTERS DATED 20 FEB 79 AND CHANGES THROUGH CHANGE 53, 29 JAN 86.

1. SUMMARY OF PROBLEM.

A. FEEDBACK FROM THE FIELD INDICATES THAT INSPECTION CRITERIA OF REFERENCE C(1) MESSAGE WERE MORE STRINGENT THAN NECESSARY. THE INSPECTION CRITERIA HAVE BEEN REVIEWED. THIS MESSAGE REVISES THE INSPECTION CRITERIA.

B. THE PURPOSE OF THIS MESSAGE IS TO PROVIDE THE NEW INSPECTION CRITERIA. COMPONENTS/AIRCRAFT WHICH HAVE PREVIOUSLY PASSED THE ORIGINAL INSPECTIONS NEED NOT BE REINSPECTED. THOSE REJECTED UNDER THE ORIGINAL CRITERIA SHOULD BE RE-EVALUATED TO DETERMINE IF THEY NOW PASS.

2. PRIORITY CLASSIFICATION - SUBPARAGRAPH 2F IS REVISED TO:

F. COMPONENTS IN STOCK AT ALL LEVELS - UNITS WILL INSPECT COMPONENTS LISTED IN PARAGRAPH 4 BELOW PRIOR TO INSTALLATION.

3. END ITEMS TO BE INSPECTED - NO CHANGE

4. ASSEMBLY COMPONENTS TO BE INSPECTED - NO CHANGE

5. PARTS TO BE INSPECTED - NO CHANGE.

PAGE 3 RUCIFRD8774 UNCLAS

APPLICATION - SUB PARAGRAPH 6D IS REVISED TO

D. PUBLICATIONS WHICH REQUIRE CHANGE -

(1) REFERENCE C(2) WILL BE REVISED TO REQUIRE PULL TEST ON OUTER RING TRUNNIONS ONLY.

(2) REFERENCE C(2) WILL BE REVISED TO REQUIRE INSPECTION PRIOR TO INSTALLATION.

(3) REFERENCE C(2) WILL BE REVISED TO ALLOW SCRATCHES UP TO .025 INCH DEPTH IN BORES.

7. SUPPLY/PARTS AND DISPOSITION - NO CHANGE.

8. SPECIAL TOOLS/JIGS AND FIXTURES - NO CHANGE.

9. INSPECTION PROCEDURES - DELETE EXISTING PARAGRAPH AND REPLACE WITH (SEE REF C(2), CHAPTER 5).

A. INSPECT ALL FIVE TRUNNION BEARINGS (FIGURE 5-34, ITEM 10) PER PARAGRAPH 5-602 FOR WEAR, UNIBALL CRACKS AND PROPER INSTALLATION. TRUNNION BEARING P/N KSP9001-3/5 SHALL BE CHECKED FOR CRACKS ON BOTH SIDES OF THE UNIBALL USING MAGNIFICATION FROM 5 TO 10 POWER.

B. CHECK TWO TRUNNION IN THE OUTER RING FOR PROPER INSTALLATION. DISASSEMBLE AS FOLLOWS AND CONTINUE INSPECTION -

(1) DISCONNECT DRIVE LINKS FROM SWASHPLATE OUTER RING (2 PLACES) PER PARAGRAPH 5-786.

PAGE 4 RUCIFRD8774 UNCLAS

(2) REMOVE TRUNNION BEARINGS PER PARAGRAPHS 5-62 F AND H.  
DURING REMOVAL OF NUTS AND BOLTS OR DAMAGE ON THE SHANK OF  
THE BOLTS MAY INDICATE IMPROPER INSTALLATION.

C. CHECK EACH TRUNNION SHAFT FOR FRETTING WEAR OR OTHER DEFECTS.

D. CHECK OUTER RING BORES FOR SCRATCHES. SCRATCHES UP TO .005  
INCH DEPTH AND WIDTH ARE ACCEPTABLE IN BOTH INNER AND OUTER RING  
BORES.

E. INSTALL SERVICEABLE TRUNNIONS IN SWASHPLATE PER REF C PARA  
5-66 S AND T. DO NOT INSTALL BOLTS, REF C(2), FIGURE 5-37, ITEMS  
27, 32, AND 37. PERFORM PULL TEST PER WARNING NOTE ON PAGE 5-84,  
CHANGE 47. COMPLETE INSTALLATION OF TRUNNIONS PER PARAGRAPH 5-66

J.  
NOTE - BOLTS MUST BE PUSHED THROUGH BY HAND AND BE PERFECTLY ALIGNED  
WITH THE GROOVES ON TRUNNION SHAFT TO AVOID SAFETY OF FLIGHT CONDI-  
TIONS.

F. CONNECT DRIVE LINKS TO SWASHPLATE OUTER RING PER PARAGRAPH  
5-84C OF REFERENCE C(2).

10.- CORRECTION PROCEDURES - NO CHANGE

11.- WEIGHT AND BALANCE - NO CHANGE.

12. RECORDING AND REPORTING REQUIREMENTS - NO CHANGE

PAGE 5 RUCIFRD8774 UNCLAS

13. POINTS OF CONTACT.

A. FOREIGN MILITARY SALES (FMS) RECIPIENTS REQUIRING  
CLARIFICATION OF ACTION ADVISED BY THIS MESSAGE SHOULD CONTACT CW4  
LL SANSOM, AUTOVON 693-2126 OR COMMERCIAL (314) 263-2106.

B. TECHNICAL POINT OF CONTACT FOR THIS MESSAGE IS MR. KEN  
LUBER, AUTOVON 693-1675 OR COMMERCIAL (314) 263-1675.

C. LOGISTICAL POINT OF CONTACT FOR THIS MESSAGE IS MR. DEAN  
BEASTROY, AUTOVON 693-1228 OR COMMERCIAL (314) 263-1220.

D. FORMS AND RECORDS POINT OF CONTACT FOR THIS MESSAGE IS MR.

TOY BERRIO, AUTOVON 693-1955 OR COMMERCIAL (314) 263-1955.

E. MESSAGE POINT OF CONTACT IS MR. LYELL MYERS, AUTOVON  
693-3300 OR COMMERCIAL (314) 263-3300.

BT

OCTUZYUW RUCIFRD8774 1390139 MTMS-UUAC

NNNN

47552:25VDFL

Time. 08:08 05/19/86 ???

Connect Time : 168 seconds

CY MSG # TIME RADAY PRIORITY  
47129 0351 219/86

320800 940TH 453FTS AERO ACP ABC//CC FTW/CC 2034155 CONSEC 11

DPC DPM TAGM LGS LGT NA NAVY HCRX OSI OT SE SC T/A

CTUZEXW RULNEARSLSD 2190330-UPOU--RUMHDTA.

070000

070000Z AUG 86 ZEX

H HCRXNG OAC AFG HQ//HQB-AVM-LN//

O AIG 7401

CCT DA-BHCSVD

DL1900Z AUG 86

H CDRAVSCOM STL HQ//ANSV-WE//

O AIG 8881

TG 9004

TG 8708

TG 7515

TG 9042

UEHRO/AMEMB ROME IT //ODC/ PASS TO HQ RFO//

UECRFA/US EVN PROT AGY BLDG 209 HELICOPTER OPS WOODBRIDGE

UAVE EDISON NJ 08837//

UCLRFA/HQAA OFC OF ACFT OPERATIONS ACFT MAINT DIV MIAMI FL

UJ3102 (TELEX NO 808199)//

UEHIIH/AIT TAIPEI TAIWAN

UEHC/AIT WASH DC

UEHSH/COMUSMILGP SAN SALVADOR ES //SCES-AF//

UEHTG/COMUSMILGP TEGUCIGALPA HO

UEHUG/COMUSMILGP BOGOTA CO //SCCD-AFDCH//

UEHHA/COMJTF-6 PALMEROLA AB HQ //AVM//

UEHDA/COMNICOB REDSTONE ARS AL //ANSMI-ST//

UEVHAD/US CUSTOMS SERVICE DEPT OF TREASURY WASH DC

ARMY

ARMY  
DEST

UB-1-86-08  
sample

PAGE 02 RUCIFRDSLSB UNCLAS

INFO RUFNTV/CUSDAO TEL AVIV IS //MFO//

UEHC/SECSTATE WASH DC //HEA/MFO//

UECUSA/AC SCOTT AFB IL //LHMW/DVV/ICF//

UEFLAER/USDOCO LANDSOUTHEAST IZMIR TU //AV//

UECPHA/DISC PHILA PA //DEBB-JU//

UEHDT/CJUSMAG BANGKOK TH

UAYAC/HDSCLGENG MELBOURNE AS //DAIRENG//

UAYPP/DEFAIR CANBERRA AS //DAIRENG-AF/DMEL-AF//

UEHKEE/AUSTAIR WASH DC //SEHGO//

UEHDFL/USDA FOREST SERVICE PO BOX 2417 WASH DC

//COOPERATIVE FIRE PROTECTION//

UECPCLA/LOG COM OTTAWA CAN //DTHEN L-2//

UAT RUNJDK/USDAO DHAKA BG

ACCT DA-BHCSVD

BT

UNCLAS

SECTION 01 OF 02

AIG 9004 TAKE FOR INFO ONLY

AIG 8708 TAKE FOR INFO ONLY

AIG 7515 TAKE FOR INFO ONLY

PAGE 03 RUCIFRDSLSB UNCLAS

07 AUG 1986