



Rub Your Bird the Right Way

Keep your bird's tailboom skin off the bumpy road to ruin by replacing missing rubber bumpers on access doors. When bumpers, NSN 5340-01-054-1588, come off, engine vibration does a number on the Huey's soft aluminum skin. The area where the bumper should be can even wear right into the skin it's touching! That'll send the aircraft to support.

