

UH-1 Huey...

Draining APU Water

KEEP MY
INSIDES DRY
TO BE READY
TO FLY!

Dear Editor,

After washing our Hueys, water stands in the forward compartment of the APU connector. If you don't drain it ... **CORROSION!** We solved the problem by drilling a $\frac{7}{32}$ -in hole at Fuselage Station (FS)226 and



Butt Line (BL)11.50L. The area can be found by using the diagrams in Chap 2 of TM 55-1520-210-23-1.

John C. Beckman
Ft Hood, TX

(Editor's note: Battling corrosion is a top priority! AVSCOM OK's your fix. It's good to see another knockout punch delivered.)