

RCV REC # TIME RADAY  
10519 2023 330/85

IMMEDIATE

3 NM 340TH 453FTS 2CAF AERO ACD ACF ADC ACE-DET ABC/CC FTW/CC AUDITOR  
CAP CONN COMSEC DAPD W/DO DOJ DDDC DDDO DDDZ DDTM DPC DPM PCS  
JA LCC LGS LGT MA NAVY NCAX OSI OT PA SE SG SS SSF SV T/A WEA XPNT XPR

0CTUZEXW RULNEAA7704 3302015-UUUU--RUMMDTA.

ZNR UUUUU

0 261730Z NOV 85 ZEX

FM ARNG OAC AFG MD//MGB-AVN-L//

TO AIG 7401

RUIGSHA/TAG ST CROIX VQ

ACCT DA-BHCSVD

0 261400Z NOV 85

FM CDRAVSCOM STL MO //AMSAY-NE//

TO AIG 8881

AIG 9004

AIG 8708

AIG 7515

RUFHRO/US EMBASSY ROME ITALY //ODC/PASS TO HQ MF0//

RUFYDA/US EYN PROT AGY REGION II 20 FEDERAL PLAZA NY NY

RUCLFOA/MOAA OFC OF ACFT OPERATIONS ACFT MAINT DIVISION

//MIAMI FL 33102 (TELEX NO 808199)//

RUFHIN/AIT TAIPEI TAIWAN

RUFHC/AIG WASH DC

RUFHSH/COMUSMILGP SAN SALVADOR ES //SCES-AF//

RUEHTG/COMUSMILGP TEGUCIGALPA HO

RUEHBO/COMUSMILGP BOGOTA CO //SCCD-AFDC//

R DHA/COMJTF-B CONAYAGUA HO //J-E//

RULDCDA/CDRNICOM REDSTONE ARS AL //ANSMI-ST//

INFO RUENTV/CUSDAO TEL AVIV ISRAEL

RUFHC/SECSTATE WASH DC //NEA/MF0//

RHCURAA/MAC SCOTT AFB IL //LCNWB/DOV/IGF//

22

Army  
R.R.  
2022

PAGE 02 RUCIFRD7704 UNCLAS

RUFLAER/USDOC LANDSOUTHEAST IZMIR TU //AV//

RUSOPMA/DISC PHILADELPHIA PA //QEBB-JU//

RUEHDT/CMUSMAC BANGKOK THAILAND

RAYAAC/MOSCENG MELBOURNE AS //SOAIRENG//

RAYVPP/DEFAIR TECH CANBERRA AUSTRALIA //DAIRENG-AF/ORHEL-AF//

RUFAPKE/AUSTAIR WASH DC //SENGS0//

RUFYDF/USDA FOREST SERVICE PO BOX 2417 WASH DC

//COOPERATIVE FIRE PROTECTION//

RCCPCLA/LOG COM OTTAWA CAN //DTHEN 6-2//

ACCT DA-BHCSVD

BT

UNCLAS

AIG 9004 TAKE FOR INFO ONLY

AIG 7515 TAKE FOR INFO ONLY

AIG 8708 TAKE FOR INFO ONLY

SUBJECT - SAFETY-OF-FLIGHT, MAINTENANCE MANDATORY RCS CSGLD-18LD (R1

)

D. C/H/H/Y AND EH-1H/X HELICOPTERS, REVISION TO ONE TIME INSPECTION

OF CONNECTING LINKS (UH-1-85-12)

A. REPORTING SUSPENSE DATE - N/A OF THIS MESSAGE.

B. TASK/INSPECTION SUSPENSE DATE - N/A.

NOT BEEN TRANSMITTED TO UNITS SUBORDINATE TO ADDRESSEES. ADDRESSEES

UH-1-85-12  
Sewo connecting  
links  
Rev to  
UH-1-85-11

SOP-116

PAGE 03 RUCIFRD7704 UNCLAS

SHOULD IMMEDIATELY RETRANSMIT THIS MESSAGE TO ALL SUBORDINATE ACTIVITIES OR ELEMENTS AFFECTED OR CONCERNED. THE ADDRESSEES SHOULD REFERENCE THIS MESSAGE. ACTION ADDRESSEES SHOULD VERIFY THIS RETRANSMISSION WITH THE AVSCOM, AVSCOM (SOP COMPLIANCE OFFICER).

C. REFERENCE - AVSCOM MESSAGE 121400Z NOV 83, 8300 - SUBJECT-UP-FLIGHT, MAINTENANCE MANDATORY, RCS CSGLD-1&6 (R1), UH-C/M/H/V AND EH-1H/X HELICOPTERS, ONE TIME INSPECTION OF CONNECTING LINKS (UH-1-85-11) (TB 55-152D-242-2D-18).

1. SUMMARY OF PROBLEM - THE REFERENCE C MESSAGE DIRECTS REMOVAL OF SPECIFIED CONNECTING LINKS. IT IDENTIFIES A SERVICEABLE LINK AS ONE HAVING A DATA PLATE PERMANENTLY BONDED TO THE TUBE WITH THE PART NUMBER AND FSCN, THE NSN, AND A SERIAL NUMBER. THIS INFORMATION IS IN ERROR. THE DATA PLATE IS AN ADHESIVE BACKED METAL FOIL TAG AND THE DATA DOES NOT INCLUDE THE NSN.
2. PRIORITY CLASSIFICATION - NO CHANGE FROM REFERENCED MESSAGE.
3. END ITEMS TO BE INSPECTED - NO CHANGE.
4. ASSEMBLY COMPONENTS TO BE INSPECTED - NO CHANGE.
5. PARTS TO BE INSPECTED - NO CHANGE.
6. APPLICATION - NO CHANGE.

PAGE 04 RUCIFRD7704 UNCLAS

7. SUPPLY/PARTS AND DISPOSITION - NO CHANGE.
8. SPECIAL TOOLS, JIGS AND FIXTURE REQUIRED - NO CHANGE.
9. PROCEDURES - REVISE PARAGRAPH 9A OF REFERENCED MESSAGE TO READ -  
"LOCATE THE APPLICABLE CONNECTING LINK AS CITED IN PARAGRAPH 3 ABOVE. PERFORM A VISUAL INSPECTION FOR PRESENCE OF A METAL FOIL IDENTIFICATION TAG ON THE BARREL. THE IDENTIFICATION TAG MUST HAVE THE PART NUMBER AND FSCN, AND A SERIAL NUMBER. SOME LINKS MAY HAVE METAL DATA PLATES ALREADY BONDED ON THEM. IF THE SERIAL NUMBER OF A LINK CAN BE POSITIVELY IDENTIFIED UNITS ARE AUTHORIZED TO REPLACE ANY LOOSE OR MISSING METAL FOIL TAG WITH A METAL DATA PLATE BONDED TO THE TUBE. THIS DATA PLATE SHOULD CONTAIN THE PART NUMBER AND SERIAL NUMBER. FUTURE PROCUREMENTS WILL REQUIRE BONDED METAL PLATES.
10. CORRECTION PROCEDURES - NO CHANGE.
11. WEIGHT AND BALANCE - NOT APPLICABLE.
12. RECORDING AND REPORTING REQUIREMENTS - NO CHANGE.
13. POINTS OF CONTACT -
  - A. FOREIGN MILITARY SALES (FMS) RECIPIENTS REQUIRING CLARIFICATION OF ACTION ADVISED BY THIS MESSAGE SHOULD CONTACT AVSCOM, CW3 LLOYD SANSON, ATTN-AMSAY-10E, AUTOVON 693-2106 OR COMMERCIAL (314) 263-2106.

PAGE 05 RUCIFRD7704 UNCLAS

B. UH-1 TECHNICAL POINT OF CONTACT FOR THIS MESSAGE IS MR. KEN LUBER, AMSAY-EI, AUTOVON 693-1675 OR COMMERCIAL (314) 263-1675.

BT

14