

MIL-1-5606  
contaminated  
hydraulic fluid

GEN-76-9

13 APR 76 03 27Z

ARMY

13

TTUZYUW RUEAUSA#697 1040240-UUUU--RUWMDTA  
ZNR UUUUU  
130215Z APR 76  
FM NGB-ARLIT WASHDC  
TO AIG 7401  
INFO RULNEAA/ARNG-OAC EDGEWOOD ARSENAL MD//AVN-L//  
RUEAUSA/NGB WASHDC//NGB-ARLIT//  
072032Z APR 76  
FM CDR USAGMPA NEW GUMB PA//STSGP-ET//  
TO AIG 8823  
TO AIG 8824  
INFO RUEBDSA/CDR DFGO CAM STA ALEX VA//DFGO-TB//  
RUCLBGA/CDR DFGO RICH VA//DFGO-OB2//

BT  
UNCLAS  
SUBJ: CONTAMINATED HYDRAULIC FLUID, NSN 9130-00-1223-4134, CONTRACT  
DSA 600-7410-1368, ROYAL LUBRICANTS CO, LOT 73, MIL-H-5606,  
A, DFGO RICH VA, MSG DTG PR 061638Z, APR 76, SAB (GEN-76-9)  
REF A REPORTED SUBJ PRODUCT FOUND TO CONTAIN APPROXIMATELY THIRTY PER  
CENT WATER.  
2. RECOMMEND ALL ARMY ACTIVITIES UNDER YOUR COMMAND BE NOTIFIED TO  
PLACE SUBJ MATERIAL IN HOLD STATUS; REPEAT, PLACE ONLY ROYAL  
LUBRICANTS CO LOT 73, CONTRACT DSA 600-7410-1368 IN HOLD STATUS,  
3. REPORT LOCATIONS AND QUANTITIES OF SUBJ PRODUCT PLACED IN HOLD  
STATUS TO DFGO, RICH, VA//DFGO-OB2// WITH INFO COPY TO USAGMPA//  
STSGP-ET// BY 21 APR 76, NEGATIVE REPLIES NOT REQUIRED.  
4. FURTHER ANALYSIS WILL BE PERFORMED TO VERIFY SUSPECTED CONTAMINATION,  
DISPOSITION INSTRUCTIONS WILL FOLLOW.

#8697

NONE ON HAND