



When you Cobra hotshots make with a "hands on" check of the main rotor dual hydraulic servo cylinders during inspections, it's no sweat if the cylinder barrels turn. If there is no vertical movement, the servos are serviceable.

You'll find all the servo inspection info in TM 55-1520-221-20 (Dec 75) . . . Chap 6.

