

Bearings Only

Dear Windy,

TM 55-1520-210-PM (Dec 76) calls for replacing the Huey oil cooler turbine bearings on the 4th and 8th phased inspection.

But, shouldn't the blower be listed for overhaul in Chap 3 of the organizational maintenance pub?

SSG A. M.



ONLY REPLACE BEARINGS

BUG OFF, BUDDY!

YOU AIN'T OVERHAULIN' MY BLOWER IN THE FIELD!

?

Dear Sergeant A. M.,

No, even though the blower was once listed in the overhaul and retirement schedule.

The engineers at the head shed (TSARCOM) do not want the assembly overhauled in the field—just inspected and the bearings replaced.

Course, you have to get help from support since the bearing change poop is in TM 55-1520-210-34 (Sep 71).

Windy