Get a Thermometer

Inspecting the overheat switch in your bird's heater system is a guessing game without a thermometer. You have to make sure the switch contacts open at 225°F ±8° and close at 260°F ±6°, like it says in Para 13-110 of TM 55-1520-210-23-2.

A thermometer is being added to your special tools list, but until it's added, use self-indicating thermometer, NSN 6685-00-291-1003. It's not on the AMDF, so order on a DD Form 1348-6. The RIC is S9G and it costs \$29.03. Use TM 55-1520-210-23-2 as your authority.

