

15 JAN 76

17 19z Defective coating compound
Gen-76-01

ARMY
26

RAAUZEXW RULNEAA0308 0151605UUUU--RUWMDTA,
ZNR UUUUU
R 151338Z JAN 76 ZEX
FM ARNG OAO EDGEWOOD MD //OAG-AVN-L//
TO AIG 7401
INFO RUEFHQA/CNGB WASHDC //NGB-ARL-A//
R 141935Z JAN 76 ZEX
FM ODR USAAVSCOM STL MO//AMSAV-FBG//
TO AIG 8881

BT
UNCLAS
NOTE: CLN THIS MESSAGE HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO
UNITS SUBORDINATE TO ADDRESSEES, ADDRESSEES ARE RESPONSIBLE
FOR DISSEMINATION OF MESSAGE TO ALL SUBORDINATE UNITS,
ACTIVITIES, ELEMENTS, OR FOREIGN USERS AFFECTED OR CONCERNED;
RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.
SUBJ: CLN MAINTENANCE ADVISORY MESSAGE ON DEFECTIVE COATING
COMPOUND (GEN 76-1)

A. MSG R082052Z JAN 76 FM AMCI & SA, SUBJECT: ALERT NOTIFICATION
COATING COMPOUND,
1. ELASTIC COATING COMPOUND, STRIPABLE, MIL-TO-6794 SUPPLIED BY
SF. YLAT CORP UNDER PURCHASE ORDER K-W-28376-1 FOR NSN'S AND

PAGE 2 RULNEAA0308 UNCLAS
BATCHES LISTED BELOW ARE DEFECTIVE CLNNSN BATCH COLOR
R030-00-721-9380 D-8668 BLACK
R030-00-297-0189 D-8696 WHITE

2. YOUR ACTIVITY MAY HAVE RECEIVED THIS MATERIAL BETWEEN
OCTOBER THROUGH DECEMBER 1975.
3. REMOVE ALL STOCK OF ABOVE MATERIAL FROM SERVICE AND HOLD
PENDING DISPOSITION INSTRUCTIONS, SUBMIT SF 368 (MILITARY) TO
GSA, FSS, KANSAS CITY, MO, NLT 31 JAN 76.
4. NEGATIVE REPLIES NOT NECESSARY.
5. POINT OF CONTACT FOR FURTHER INFORMATION IS JOHN O. TRESSLER,
DIR ORDER PROCESSING & CONT. DIV, GSA, FSS, POC, WASH DC.

BT
#0308