



The old bit about a mechanic not being able to do a job without tools was never truer than on the Huey (UH-1C) 540 rotor system.

It's a capital idea to inventory your special tools with TM 55-1520-210-20P (Dec 66) and TM 55-1520-210-35P-2 (Jan 67) to make sure you have the new tools needed to maintain your Charlie Model 540 rotor system.

Requisition any missing tools—you bet!

THIN SOCKETS ARE HERE



HEP! HEP! I'M A THIN-WALLED CAT THAT'S FAT ON THE INSIDE, YESSURR!

Grab that spanking new Aircraft General Mechanic's Tool Kit and make yourself a note. FSN 5120-914-9205 gets you a 7/8-in spark plug socket; FSN 5120-914-9120 does the same for the 13/16-in size. SC 5180-93-CL-A01 (Sep 66) was put together before FSN's for these 2 sockets became available. So check out those in your kit to see if you've got 'em.