


PUB WILL CLUE YA

One glance at the Huey parts pub will clue you that the C/M model door hinge rotor pylon is not the same as the one for the D/H model.

Some stabilizer bar weights have been switched. Sure, the wrong weights will fit on the bar but you'll add additional stress on the bar that will shorten bearing life.



The stabilizer weights carry different part numbers for each type of pylon. Never mix 'em.

