

RCV MSG # TIME RA
02468 2222 316/85

IMMEDIATE

3208HV 940TH 453FTS 2CAF AERO ACD ACF ADC ACE-DET ABG/CC FTW/CC AUDITOR
CAP COMR CONSEC DAPD W/DG DOJ D00C D00S D00Z D0TH DPC DPH FCS
A LGC LGS LGT NA NAVY NCAX OSI OT PA SE SG SS SSF SV T/A WEA XPMT XPR

OCTUZEXW RULNEADILL 316217Z ~~0000~~ ~~000000~~

ZNY 00000

0 122100Z NOV 85 ZEXW

FM ARMG OAC APG MD//MGB-AVH-L//

TO AIG 7401

RULGSKA/TAG VO ST CROIX VO

ACCT DA-BHCSVD

0 121700Z NOV 85

FM CDRAVSCOM STL HQ //ANSAV-NE//

TO AIG 8881

AIG 9004

AIG 8708

ACCT DA-BHCSVD

BT

UNCLAS

SECTION 01 OF 02

AIG 9004 TAKE FOR INFO ONLY

AIG 8708 TAKE FOR INFO ONLY

SUBJECT - SAFETY OF FLIGHT MESSAGE, MAINTENANCE MANDATORY, RCS
CSGLD 1860 (R-1). EH-1 SERIES AIRCRAFT, ONE-TIME AND RECURRING
INSPECTION OF ALTERNATOR WIRE BUNDLE AT FUSELAGE STATION 133. (SOF-UH)

1-85-10 TB 55-1520-247-20-1.

IPENSE DATE -

A. REPORTING SUSPENSE DATE - 15 DAYS AFTER RECEIPT OF THIS MESSAGE.
B. TAPKING/INSPECTION SUSPENSE DATE - 10 HOURS OR 15 DAYS (WHICHEVER
COMES FIRST) AFTER RECEIPT OF THIS MESSAGE.

NOTE - THIS IS A SAFETY OF FLIGHT MESSAGE, MAINTENANCE MANDATORY,
THIS MESSAGE HAS NOT, REPEAT, HAS NOT BEEN TRANSMITTED TO UNITS

PAGE 02 RUCIFRDL405 UNCLAS

SUBORDINATE TO ADDRESSES. ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT
THIS MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR ELEMENTS AFFECTE
D

OR CONCERNED. THE RETRANSMITTAL SHALL REFERENCE THIS MESSAGE.

ACTION ADDRESSEES WILL IMMEDIATELY VERIFY THIS RETRANSMISSION TO
COMMANDER, AVSCOM, ATTN - ANSAV-MEM (SOF COMPLIANCE OFFICER).

C. REFERENCES -

(1) TM 55-1520-210-23 AVIATION UNIT AND INTERMEDIATE MAINTENANC

E
MANUAL AND INSTRUCTIONS ARMY MODEL UH-1H/V/EH-1H HELICOPTERS,
20 FEB 79.

(2) TM 55-1520-210-PMD, UH-1H/V AND EH-1H/X AIRCRAFT PREVENTIVE
MAINTENANCE DAILY INSPECTION CHECKLIST, 11 JAN 83.

(3) TM 55-1520-210-PM, UH-1H/V AND EH-1H/X PHASED MAINTENANCE
CHECKLIST, 18 APR 85.

SUMMARY OF PROBLEM - SEVERAL EIR REPORTS HAVE BEEN RECEIVED
L THIS COMMAND CONCERNING CHAFING OF THE ALTERNATOR WIRE BUNDLE
ON THE FORWARD TRANSMISSION FAIRING MOUNTING BRACKET LOCATED ON
THE ROOF OF THE HELICOPTER AT FUSELAGE STATION 133. THE PURPOSE
OF THIS MESSAGE IS TO INSPECT ALL EH-1 SERIES AIRCRAFT FOR CHAFING
OF THE ALTERNATOR WIRE BUNDLE AND TO REPOSITION OR REINSULATE ANY

ARMY

RM
2220
PU

UH-1-85-10
alternator
wire bundle

SOF 9