

3 Jul 79 15 05z

UZEXW RULNNAC1732 1841423-UUUU--RUWMDTA.

UUUUU

313472 JUL 79 ZEX

ARNG-OAC EDGEWOOD MD//NGB-AVN-L//

AIG 7401

7305

218107 JUL 79

CDRUSTSARCOM STL MO //DRSTS-SAJ(2)//

AIG 8879

LAS

E CLN THIS IS A SUPPLY ADVISORY MESSAGE AND HAS NOT,  
EAT HAS NOT, BEEN TRANSMITTED TO UNITS SUBORDINATE  
ADDRESSEES. ADDRESSEES SHOULD IMMEDIATELY RETRANSMIT  
S MESSAGE TO ALL SUBORDINATE UNITS, ACTIVITIES OR  
MENTS AFFECTED OR CONCERNED.

J-CLN ROLLER CHAIN-KIT, NSN 1615-01-047-8614, UH-1B,  
H, M AIRCRAFT.

USATSARCOM MSG 291658Z JAN 79, SUBJECT AS ABOVE.

REFERENCED MESSAGE ADVISED THAT ROLLER CHAIN KIT

NO LONGER AVAILABLE AND THAT INDIVIDUAL LISTED COM-  
EN SHOULD BE REQUISITIONED. THE AVAILABILITY

E 2 RULNNAC1732 UNCLAS

E FOR THE ROLLER CHAIN, NSN 3020-01-048-3468, WAS  
TED AS 1 MAY 79. DUE TO CONTRACTUAL PROBLEMS, THIS  
E HAS NOW SLIPPED TO 1 NOV 79.

DUE TO A VERY CRITICAL SUPPLY POSITION FOR THE  
IN, IT IS REQUESTED THAT A THROUGH INVENTORY BE  
E TO DETERMINE IF ANY EXCESS KITS (NSN 1615-01-047-  
4) ARE AVAILABLE FOR RETURN TO THE NICP DEPOTS.  
RE WERE ENOUGH KITS FABRICATED TO RETROFIT THE  
PLETE UH-1 FLEET; HOWEVER, EXCESSIVE QUANTITIES WERE  
UISIONED BY SOME ACTIVITES.

KITS SHOULD BE RETURNED TO RED RIVER ARMY DEPOT,  
ARKANA, TEXAS, M/F NICP ACCOUNT 5-3725. POINT OF  
TACT THIS COMMAND IS MS WILMA RICE, AUTOYON 593-  
4. COMMERCIAL, 263-0534.

32

27