

UH-1 Huey...

Stabilizer Hardware Change

Flat washers under the mounting bolts for your Huey's stabilizer let the bolts vibrate loose. A loose stabilizer damages the bird's hub.

So replace those flat washers as soon as possible with countersunk washer, NSN 5310-00-149-9146, like it says in AVSCOM Msg UH-1-90-ASM-01.

Then torque the bolts to 175 lb-in like it says in Fig 5-5 of TM 55-1520-210-23-1.

